



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
PHAY KOK BENG 576 WOODLANDS DRIVE 16 #10-506 SINGAPORE 730576 Contact No	Cust No/Name KCV16118/PHAY KOK BENG Reg No/Reg Date SMV55338 / 07/10/202 Date In/Mileage / 0 Chassis No MMBSTA13AMH001323 Engine No 3A92UJS5665 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31) Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV16118	CRDVCH	19/04/2021/ 18:02	Bod	442 / CocoLu	10246

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER				640 700.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER				2 550.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80 100.00
M SUNDRY Sundry				20.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				280.00
M FACE,RR BUMPER	1.00	654.00	00.00	654.00

# Estimate

stere CLKK) WL PL  
12/5/21, 10.30 am  
P/P  
My Bel SL  
3 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Signature:  
Date:

Nett	2,304.00
7% GST on	2304.00
Total Payable	2,465.28

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.