

AUBURN AUTO PTE LTD

UEN 200805305G

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : 96191525

Email : auburnauto.work@gmail.com

VEHICLE NUMBER: SJU9806D. HONDA STREAM

Quantity	Description	Repairer's estimate
1	Front bumper CRU ✓ CRU	635 ✓ 760.00 ✓ 635.00
1	Left headlight X NN X NN	680.00
1	Left fender X NN X NN	270.00
6	Bumper clips NEC ✓ NEC	18.00 ✓
	TOTAL	1,728.00
	<u>Labour & Misc</u>	
	Labour to remove front bumper and replace new bumper, fender and headlamp	200 800.00 200
	To check and reconnect all necessary wiring	30 100.00 30
	To spray paint into similar colour	200 480.00 200
	TOTAL LABOUR & PARTS	\$3,108.00 952.40
		L/S- 761.92

Steve (Lkk) 21/4/21

w/p

L/S

Resurvey After spray
3 days

= 750 ✓