

ASS. REC. BY:

REF:

AG / CS/AIG21004934/Kvf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 0999993650

Claims No. 6339460042SG

Sum Insured:

Excess:

1900

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$54K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.13.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

15/6/21

Final fig \$5523.10 confirmed by email (Red 2970,35%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

a 15/6/21-Typist

Report Format: Merimen

Lump Sum / I.B.I: (\$ 5523.10)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Fuel

Others

TOTAL

Veh No:

GBG-9738K Yr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mr Citan 10900 1461

Colour

White AC: Insured / Std / Nil / NA

Sp. Reading

59408 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

WOF 4156052U 221537

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: GY 195/65R15

R: Nil

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

4 mm

R/Bal.

4 mm

L/Bal.

4 mm

L/Bal.

4 mm

D.O.A.

7/4/21

D.O.I.

20/4/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rm

The U/C / Chassis frame / Body Structure affected due to collision.



REF: AIG

TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 07/04/2021

ESTIMATE

NO : QUOT202104-000019(00)

DATE : 20/04/2021

POLICY NO : 999995580

VEH REG NO : GBG9738K

MAKE/MODEL : MERCEDES BENZ CITAN 109
CDI EL 5MT 6DR

CHASSIS NO : WDF4156052U221537

ENGINE NO : K9KE628D403982

REG. DATE : 2017

*Not Authorized
Mercury Bepaim
5 days***Estimate Repair Cost to Vehicle No : GBG9738K**

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Support Panel	1	450.00	CM 450.00 ✓
2 Headlamps assy - RH	1	580.00	CM 580.00 ✓
3 Front apron panel	1	210.00	Sn 210.00 X
4 Front apron centre emblem	1	58.00	nn 58.00 X
5 Front apron emblem nuts	2	7.00	nn 14.00 X
6 Front fender - RH	1	320.00	Bu 320.00 ✓
7 Front fender inner shield - RH	1	185.00	185.00 ?
8 Front fender inner shield clips - RH	20	5.50	nn 110.00 ✓
9 Front bumper	1	1,080.00	CM 1,080.00 ✓
10 Front bumper inner frame	1	125.00	125.00 ?
11 Front bumper reinforcement	1	450.00	R 450.00 X
12 Front bumper side bracket - RH	1	42.00	CM 42.00 ✓
13 Front bumper top panel (inner)	1	295.00	295.00 ?
14 Front bumper centre grille	1	98.00	98.00 ?
15 Front bumper fog lamp cover - RH / LH	2	98.00	196.00
16 Front bumper fog lamp - RH	1	115.00	115.00 ?
17 Front bumper towing cover	1	28.00	ni 28.00 ✓
18 Front bumper under cover	1	115.00	Sn 115.00 X
			4,471.00
		Add 10%	447.10
			4,918.10
SPECIAL NET			
19 Front number plate	1	40.00	Sn 40.00 X
			40.00
LABOUR			
20 To remove and refit air-con condenser, pipes and refill air-con gas	1	150.00	150.00 100%
21 To check and rectify wiring system	1	80.00	80.00 20%
22 To panel beat and straighten bonnet, RH front fender inner panel, front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 50%
23 To putty & spray paint on affected areas	1	1,200.00	1,200.00 60%
24 To reset and re-programme headlamp fault code	1	250.00	250.00 ?
			2,680.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SA0A2148000C-01 / AIGI Pte Ltd
 ENTRY DATE & TIME: 08/04/2021 23:30 (SGT)
 SUBMITTED BY: Sabina
 VERSION: 2 (12/04/2021 19:19 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/04/2021 23:30 (SGT)
Date of Accident	07/04/2021 13:00 (SGT)
Exact Location of Accident	210 Tanah Merah Coast Rd, Singapore 498805
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBG9738K

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
Company Reg No	1XXXXX778Z
Email Address	derrick.lee@daimler.com
Mobile Phone No	(Phone) +65-68498118
Alternative Phone No	(Office) +65-68498118

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Citan
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	0

INSURANCE COMPANY


Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	-

DRIVER

Name of Driver	GUDLA DURGA RAO
Passport No/FIN	GXXXX218T

 Accident report SA0A2148000C

SKETCH PLAN



210 Tanah Merah
Coast Rd
(Naval Base)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

A: GBG 9738K

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
AIZAM BIN ATAN

Reporting Centre Personnel's Signature
Name:
NRC/TIN No.:

ACCIDENT STATEMENT (2000 characters)

After making a right turn. When I stepped on the brake to slowed down and stopped. The brake system seems not working. Hence I decided to swerve to the right due to avoid with vehicle in front. My vehicle ended brushed onto the building wall. Just after the incident, I took a video to show that the braking system was not functioning very well. Refer to video footage.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

8 April 2021 at 4 30 PM

Date/Time:

8 April 2021 at 4:30 PM