



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 07/04/2021

ESTIMATE

NO : QUOT202104-000019(00)

DATE : 06/05/2021

POLICY NO : 999995580

VEH REG NO : GBG9738K

MAKE/MODEL : MERCEDES BENZ CITAN 109
CDI EL 5MT 6DR

CHASSIS NO : WDF4156052U221537

ENGINE NO : K9KE628D403982

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG9738K

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
SUPPLEMENTARY PARTS			
1 Front tie-rod -- RH bent	1	255.00	255.00
2 Front tie-rod end -- RH bent	1	195.00	195.00
			450.00
		Add 10%	45.00
			495.00
LABOUR			
3 To remove and refit RH front undercarriage	1	280.00	280.00 100
4 To check wheel alignment	1	80.00	80.00 60
			360.00
TOTAL			S\$ 855.00
ADD GST @ 7%			59.85
GRAND TOTAL			S\$ 914.85

SINGAPORE DOLLAR NINE HUNDRED FOURTEEN AND CENTS EIGHTY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE