

Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : OD/042021/4819
Accident date: 17/4/2021
Your Ref : 1700029043-03

Tax Invoice:

Date : 20/4/2021

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

NOT Authorized
Repair B4 repair

85853.47

5 days
Excess to be confirmed
B4 excess

ESTIMATE COST OF REPAIRS

Vehicle No. : SKP9968J

Model : Toyota Prius

ZVW50-8032851

- 1 pc Front bonnet RH hinge
- 1 pc Front RH headlamp 2531.60
- 1 pc Front RH headlamp panel 213.50
- 1 pc Front bumper (52119-47820-E0)
- 1 pc Front bumper RH side cover (black)
- 1 pc Front bumper RH side retainer
- 10 pcs Front bumper clips @ \$3.00
- 1 pc Front bumper uncer cover
- 1 pc Front wiper tank
- 1 pc Front RH fender
- 1 pc Front RH fender inner shield
- 10 pcs Front RH fender inner shield clips @ \$3.00
- 1 pc Front RH fender "Hybrid" emblem
- 1 pc Front RH fender bracket
- 1 pc Front RH fender triangle cover

\$ R	59.90	X	
CMT	\$	2,558.10	✓
\$	220.50	✓	
\$	1,547.70	✓	
\$	81.90	X	
\$	82.32	✓	
\$	30.00	✓	
\$	144.50	X	
\$	182.50	✓	
\$	977.80	✓	
\$	155.10	✓	
\$	30.00	✓	
\$	69.60	✓	
\$	55.30	✓	
\$	129.20	✓	
\$	6,324.42		
\$	(1,581.11)		
\$	4,743.32		

Less 25%

To diagnose electrical components
To repair damages
To spray painting

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

VIN'S MOTOR PTE LTD

\$ 250.00 801
\$ 780.00 5501
\$ 880.00 7201
\$ 6,653.32