$| \triangleleft$

<	1	of 2 ?	>	Þ١	Ö	Θ	100%	~	G	Find Next	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En	Automob	ile						
	SMRT AUTOMOTI	VE SERVICES PTE LTD		Ref:	CS3/SMR21004938/T1uf3						
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 17705		Date:	20/04/2021						
				Code:	SMR						
1.		Policy Particulars :- (THIRD PARTY CLAIM)									
	Insured Veh.	SG 1734Y	Veh. Inspected	t	YQ 3011M						
	Policy No.		Coverage (\$)		0.00						
	Claim No.		Excess (\$)		0.00						
	Assign From	HUA YEN	Assign Date		20/04/2021						
2.		Vehicle Partic	ulars & Conditi	on							
	Make & Model		c.c		0						
	Engine No.	HIDDEN	Year of Reg.								
	Chassis No.		Colour								
	Odometer	-	Steering								
	Brakes		Modification								
	General										
3.		Condition	ons of Tyres								
		Size	Make		Balance						
	R/H Front Tyre				mm						
	L/H Front Tyre				mm						
	R/H Rear Tyre				mm						
	L/H Rear Tyre				mm						
4.		Description	on of Damages								
5.			ral Information								
	Accident Date	16/04/2021	Inspection Da	te	27/05/2021						
	Survey held at										
		2 YISHUN INDUSTRIAL STREE 768159	T 1, #02-06, NOR	TH POINT	BIZHUB, SINGAPORE						
5a.	Remarks										
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.										