

<< Assessment Details

- General & Workshop Details
  - Vehicle & Driver Details
  - Vehicle Condition
  - Taxes & Ratio
  - Parts & Labour
  - Miscellaneous
- Summary

General Details

Involving	TPVD Toyota Hiace (GBK4382P)
Date of Loss	17 April 2021
Time of Loss	13:10
Loss Description	SMC7983Y (INSD) << GBK4382P (TP) << SGT2202G
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="0"/>
Nett Loss Amount	\$0.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>

# Assessment Details

- General & Workshop Details
  - Vehicle & Driver Details**
  - Vehicle Condition
  - Taxes & Ratio
  - Parts & Labour
  - Miscellaneous
- Summary

## Vehicle & Driver Details

Vehicle Registration#	GBK4382P	Purchase Date	<input type="text" value="DD/MM/YYYY"/>
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="21/07/2020"/>
Mileage	<input type="text" value="33099"/>	Age of Vehicle	0

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<input type="text" value="2020"/>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	QU RONGXIN	<input type="text"/>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD Toyota	TOYOTA
Model	Hiace	HIACE VAN TURBO 4DF
Type		
Type of Paint		
Chassis No		JTFHT02P409990142
Engine No		1KDB042723
Engine Capacity		2982
Sum Insured		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		DD/MM/YYYY 
Age	0	
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		
License Type		
License Issue Date		DD/MM/YYYY 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	TBC	<input type="text"/>

# Assessment Details

- General & Workshop Details
  - Vehicle & Driver Details
  - Vehicle Condition**
  - Taxes & Ratio
  - Parts & Labour
  - Miscellaneous
- Summary

## Detailed Assessment

Inspection Date \*  

Total Loss

Towing Charges

Voluntary Excess

Compulsory Excess

Young/Inexperienced/  
Unnamed Driver Excess

## Condition of Vehicle at time of survey

General condition  

Steering (Serviceable)

Footbrake (Serviceable)

Handbrake (Serviceable)

Engine Modification

Pre-accident condition  

Other Excess

0

### Tyre Condition

---

Age of Tyres

Front Tyre Size

195 R15C

Front left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

Spare wheel

Rear Tyre Size

195 R15C

Rear left side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm

# << Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio**
- Parts & Labour
- Miscellaneous
- Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text" value="0"/>	Salvage%	<input type="text" value="0"/>
Discount%	<input type="text" value="25"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Cash Loss	<input type="radio" value="Yes"/> Yes <input checked="" type="radio" value="No"/> No	Part Supplied by
Paint Material Ratio	<input type="text" value="80"/>			

A  
X  
A

Save



Service Requests

Messages

Claims

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio **Parts & Labour** Miscellaneous Summary

Parts

<div style="display: flex; justify-content: space-around; border: 1px solid #ccc; padding: 2px;"> <span>Add</span> <span>Approve</span> <span>Deny</span> <span>Submit All</span> </div>													
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		FRONT BUMPER	Deformed	0	581	No	0	25	0	0	435.75
	0	1		FRONT BUMPER TOP BEAM	Serviceable	0	0	No	0	0	0	0	0
	0	2		FRONT BUMPER SIDE RETAINER	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT BUMPER REINFORCEMENT	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT GRILLE	Cracked	0	473	No	0	25	0	0	354.75
	0	1		FRONT CENTRE TOP PANEL	Serviceable	0	0	No	0	0	0	0	0
	0	1		HEADLAMP N/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		BONNET	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		BONNET EMBLEM LOGO	Serviceable	0	0	No	0	0	0	0	0
	0	1		BONNET LOCK	Serviceable	0	0	No	0	0	0	0	0
	0	2		BONNET HINGE	Serviceable	0	0	No	0	0	0	0	0
	0	1		AIRCON CONDENSER	Serviceable	0	0	No	0	0	0	0	0
	0	1		RADIATOR	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT DOOR N/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT DOOR PILLAR N/S	Serviceable	0	0	No	0	0	0	0	0
	0	2		FRONT DOOR HINGE N/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT QUARTER PANEL N/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT DOOR WEATHERSTRIP N/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT DOOR INNER TRIM N/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT DOOR STEP GARNISH N/S	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		INTERCOOLER	Serviceable	0	0	No	0	0	0	0	0
	0	1		WIPER WASHER TANK	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT BUMPER TOW COVER	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR WINDSCREEN MOULDING	Necessary	0	180	No	0	25	0	0	135
	0	1		TAILGATE	Dented	0	1755	No	0	25	0	0	1316.25
	0	2		TAILGATE DAMPERS	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE LOCK	Damaged	0	341.65	No	0	25	0	0	256.24
	0	1		TAILGATE LOCK CATCH	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE INNER TRIM	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE "TOYOTA" LOGO	Necessary	0	68.5	No	0	25	0	0	51.38
	0	1		SET TAILGATE KEY LOCK	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE OUTER GARNISH	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		TAILGATE WEATHERSTRIP	Cut	0	286	No	0	25	0	0	214.5
	0	2		TAILGATE SIDE STOPPER SOCKETS	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILGATE "HIACE" STICKER	Necessary	0	20	No	0	25	0	0	15
	0	1		TAILLAMP N/S	Cracked	0	365	No	0	25	0	0	273.75
	0	1		TAILLAMP PANEL INNER N/S	Repair	0	0	No	0	0	0	0	0
	0	1		TAILLAMP LOWER GARNISH N/S	Cracked	0	126.2	No	0	25	0	0	94.65
	0	1		END PANEL	Dented	0	695	No	0	25	0	0	521.25
	0	1		END PANEL INNER MEMBER	Repair	0	0	No	0	0	0	0	0
	0	1		END PANEL TOP GARNISH	Bent	0	241.55	No	0	25	0	0	181.16
	0	1		REAR BUMPER	Deformed	0	561.9	No	0	25	0	0	421.43
	0	1		REAR BUMPER STEP GARNISH	Serviceable	0	0	No	0	0	0	0	0
	0	2		REAR BUMPER LOWER BRACKET - 4PCS	Bent	0	18	No	0	25	0	0	27

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	2		REAR BUMPER SIDE RETAINER	Necessary	0	61.5	No	0	25	0	0	92.25
	0	1		REAR FLOOR PANEL	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR SPARE WHEEL CARRIER	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR SPARE WHEEL BRACKET	Serviceable	0	0	No	0	0	0	0	0
	0	2		TAILGATE SIDE STOPPER STRIKER	Serviceable	0	0	No	0	0	0	0	0
	0	2		TAILLAMP LOWER GARNISH RETAINER	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILLAMP PANEL OUTER N/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR STEP PANEL	Serviceable	0	0	No	0	0	0	0	0
	0	2		TAILGATE HINGE	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR SIDE PANEL N/S	Repair	0	0	No	0	0	0	0	0
	0	1		REAR SIDE PANEL AIR VENT N/S	Serviceable	0	0	No	0	0	0	0	0

Labour

Add	Approve	Deny	Submit All
-----	---------	------	------------

	ADD	APPROVE	DENY	SUBMIT ALL							
EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME		ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO DISMANTLE / RENEW FRONT & REAR ACCIDENT DAMAGED PORTIONS. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS		0	1200	0	0	Reviewing		
	0		TO DISCONNECT FRONT & REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS		0	60	0	0	Reviewing		
	0		TO REMOVE AND REPLACE A/C CONDENSER. TO CHECK A/C FUNCTIONALITY		0	0	0	0	Deny		
	0		TO REMOVE AND REPLACE RADIATOR. TO PERFORM PRESSURE TEST AND CHECK COOLING SYSTEM FUNCTIONALITY		0	0	0	0	Deny		
	0		TO REMOVE AND REFIT N/S FRONT DOOR COMPONENTS TO REPLACE N/S FRONT DOOR, CHECK ALIGNMENT		0	0	0	0	Deny		
	0		TO REMOVE AND REPLACE INTERCOOLER. TO CHECK FUNCTIONALITY		0	0	0	0	Deny		
	0		SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY FRONT & REAR AFFECTED AREA / PANEL		0	1200	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	0	60	0	0	Reviewing		
	0		TO REMOVE AND REFIT N/S REAR SIDE PANEL GLASS TO FACILITATE REPAIR WORK	0	0	0	0	Deny		
	0		TO REMOVE AND REFIT TAILGATE WINDSCREEN TO FACILITATE REPAIR WORK	0	120	0	0	Reviewing		

# Assessment Details

## Summary

Add
Approve
Deny
Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 10 DAYS	Reviewing	0	0		
	0	FRONT BUMPER CLIPS - 10PCS	Reviewing	0	30	NECESSARY	
	0	FRONT GRILLE CLIPS - 8PCS	Reviewing	0	20	NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	RADIATOR COOLANT	Deny	0	0	NOT NECESSARY	
	0	FRONT DOOR INNER TRIM CLIPS N/S - 8PCS	Deny	0	0	NOT NECESSARY	
	0	FRONT LICENCE PLATE & FRAME	Reviewing	0	30	BENT	
	0	FRONT DOOR COMPANY STICKER N/S	Deny	0	0	NOT NECESSARY	
	0	FRONT DOOR ADVERTISEMENT STICKER N/S	Deny	0	0	NOT NECESSARY	
	0	TAILGATE GLASS SEALANT	Reviewing	0	40	NECESSARY	
	0	TAILGATE GLASS FOAM TAPE	Reviewing	0	30	NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	TAILGATE INNER TRIM CLIPS - 8PCS	Deny	0	0	NOT NECESSARY	
	0	REVERSE SENSOR	Reviewing	0	200	DAMAGED	
	0	REAR BUMPER CLIPS - 12PCS	Reviewing	0	30	NECESSARY	
	0	TAILGATE "70KM/H" STICKER	Reviewing	0	10	NECESSARY	
	0	TAILGATE "8PAX" STICKER	Reviewing	0	10	NECESSARY	
	0	TAILGATE "TOYOTA HIACE" STICKER	Reviewing	0	55	NECESSARY	

# Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

## Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$7,485.36
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts		
Labour		
Spare Parts		
Miscellaneous		

Submit for Review



# Assessment Details

## Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FINAL LUMP SUM	Reviewing	0	6000		

# Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

## Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$6,000.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
----------	----------	----------

Miscellaneous

Submit for Review