

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorized
1/1 Day &
Resurvey After Paint
6 days

REPAIR ESTIMATE FOR SJA3833U

No.	Qty	List Items		
1	1	Front bumper	\$ Br	562.90 —
2	1	Front bumper LH side retainer	\$ Oil	50.70 —
3	1	LH headlamp	\$ Sn	572.40 X
4	1	Front LH fender	\$ Br	688.90 ✓
5	1	Front LH fender signal lamp	\$ Sn	45.80 X
6	1	Front LH fender "VVTI" emblem	\$ m	41.70 —
7	1	Front LH 1/4 glass moulding	\$	179.20 ?
8	1	Front LH fender under shield	\$ CM	275.20 —
9	1 set	Front fender under shield clips	\$ m	40.00 —
10	1	Front LH shock absorber	\$	411.70 ?
11	1	Front LH lower arm	\$	577.95 ?
12	1	Front LH knuckle arm	\$	402.31 ?
13	1	Front LH wheel hub & bearing	\$	202.90 ?
14	1	Front LH door	\$ R	1,221.90 X
15	1	Front LH door protector	\$ m	202.90 —
16	1	Front LH door checker	\$ Sn	106.75 X
17	1	Front LH door hinge (Top & bottom)	\$ R	195.00 X
18	1	Front LH door inner trim board	\$ Sn	677.50 X
19	1 set	Front LH door inner trim board clips	\$ m	60.00 X
20	1	LH rocker panel	\$ R	411.75 X
			\$	6,927.46
			Less 25%	\$ 1,731.87
			Total :	\$ 5,195.60

Special Nett Items

21	1	Front LH sports rims	\$ R	400.00 2800
22	1	Front LH tyre	\$	220.00 ?
			Total :	\$ 620.00

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	1,000.00 600
2	To putty and spray Spray Paintings charges.	\$	1,000.00 750
3	To check wirings and lightings.	\$	40.00 20
4	To remove, refit door fittings.	\$ m	80.00 X
5	To remove, refit front LH under carriages.	\$	220.00 ?
6	To conduct computerise wheel alignment test.	\$	80.00 60
7	To supply and apply anti-rust treatment	\$	100.00 30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: