



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2202671
3 ANSON ROAD #16-00	INV Date	11/05/2022
SPRINGLEAF TOWER	Reference	CC6/CTI21004946/Aga3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SJG 6848B
Insured Veh.	GBF 7721B
Claim No.	SNM21D202258/LKKDS
Policy No.	DMCVSNW00024532101
Accident Date	17/04/2021
Inspection Date	21/04/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI21004946/Aga3q2 Date: 11/05/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 7721B	Veh. Inspected	SJG 6848B
Policy No.	DMCVSNW00024532101	Coverage (\$)	0.00
Claim No.	SNM21D202258/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	21/04/2021
2. Vehicle Particulars & Condition			
Make & Model	LEXUS ES250	c.c	2487
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTHB11B1602002985	Colour	GOLD
Odometer	20572 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/45 R18	DUNLOP	6 mm
L/H Front Tyre	235/45 R18	DUNLOP	6 mm
R/H Rear Tyre	235/45 R18	DUNLOP	6 mm
L/H Rear Tyre	235/45 R18	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/04/2021	Inspection Date	21/04/2021
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 6848B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	1,135.00	1,135.00
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	54.00	-
1	FRONT SENSOR RH	DAMAGED	488.00	312.00
1	HEADLAMP RH	CUT	3,753.00	3,753.00
1	FOG LAMP GARNISH W/CHROME RH	NOT NECESSARY	252.00	-
1	FRONT FENDER RH	NOT NECESSARY	1,617.00	-
1	FRONT SPORTS RIM RH (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-729.90	-520.00
			6,569.10	4,680.00
<b><u>SPECIAL NETT ITEMS</u></b>				
10	FRONT BUMPER CLIP @\$5.00 (SN)	NECESSARY	50.00	30.00
			50.00	30.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING AND REFOCUS HEADLAMP.		50.00	30.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS .		400.00	250.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		600.00	250.00
			1,050.00	530.00
<b>GRAND TOTAL</b>			<b>7,669.10</b>	<b>5,240.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>5,240.00</b>

Report Ref No. CC6/CTI21004946/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SJG 6848B

## INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SJG 6848B

## RE-INSPECTION

