



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2201538

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 18/03/2022
Reference CC6/CTI21004947/Dea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 3422K
Insured Veh. SMP 704P
Claim No. SNM21D202259/C02
Policy No. DMPCSNA00120572001
Accident Date 19/04/2021
Inspection Date 22/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21004947/Dea3q2 Date: 18/03/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMP 704P	Veh. Inspected	SHC 3422K	
Policy No.	DMPCNA00120572001	Coverage (\$)	0.00	
Claim No.	SNM21D202259/C02	Excess (\$)	0.00	
Assign From		Assign Date	22/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU803080466	Colour	BLUE	
Odometer	280383 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/04/2021	Inspection Date	22/04/2021	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3422K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	NOT NECESSARY	458.60	-
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	112.70	-
1	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	REAR BUMPER SIDE CLIP	NOT NECESSARY	25.00	-
1	SEAL ,REAR BUMPER SIDE ,LH	NOT NECESSARY	148.40	-
1	REAR FENDER ,LH	DENTED	836.70	836.70
1	REAR FENDER SHIELD (LH)	NOT NECESSARY	174.20	-
1	PANEL SUB-ASSY ,REAR DOOR ,LH	DENTED	1,258.30	1,258.30
1	MOTOR ,POWER WINDOW REGULATOR FRT ,LH	NOT NECESSARY	941.80	-
1	REGULATOR ,FRONT DOOR WINDOW REAR ,LH	NOT NECESSARY	228.40	-
1	REAR DOOR OUTER HANDLE	NOT NECESSARY	93.00	-
1	PANEL SUB-ASSY ,FRONT DOOR ,LH	DENTED	1,264.00	1,264.00
1	FRONT DOOR OUTER HANDLE (LH)	CUT	378.90	378.90
1	FRONT DOOR INNER LOCK	NOT NECESSARY	688.80	-
1	FRONT DOOR TRIMBOARD	NOT NECESSARY	725.00	-
1	FRONT DOOR WEATHERSTRIP	SERVICEABLE	457.90	-
1	FRONT DOOR RUBBER SEAL	NOT NECESSARY	257.00	-
1	MOTOR ASSY ,POWER WINDOW FRT ,LH	NOT NECESSARY	941.80	-
1	REGULATOR ,FRONT DOOR WINDOW FRT ,LH	NOT NECESSARY	228.40	-
1	MIRROR ASSY ,OUTER REAR VIEW ,LH	NOT NECESSARY	1,728.70	-
1	ROCKER PANEL OUTER GARNISH	TO REPAIR SEE LABOUR	576.00	-
1	REAR TYRE RIM (LH)	NOT NECESSARY	1,555.00	-
1	REAR WHEEL BEARING & HUB ASSY	NOT NECESSARY	610.20	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	118.30	-
1	REAR SHOCK ABSORBER MOUNTING	NOT NECESSARY	125.30	-
1	REAR LOWER ARM	NOT NECESSARY	497.50	-
1	REAR UPPER ARM	NOT NECESSARY	356.80	-
1	REAR KNUCKLE ARM	NOT NECESSARY	810.60	-
1	REAR TRAILING ARM	NOT NECESSARY	314.20	-
1	REAR ASSIST ARM	NOT NECESSARY	342.20	-

Report Ref No. CC6/CTI21004947/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER COVER	BENT / CUT	499.90	499.90
1	FRONT SIDE MEMBER SIDE COVER	NOT NECESSARY	172.50	-
1	LAMP ASSY ,FOG ,LH	NOT NECESSARY	920.00	-
1	FRONT BUMPER SIDE RETAINER	SERVICEABLE	77.00	-
1	FRONT LOWER SIDE RAIL (LH)	NOT NECESSARY	230.80	-
1	UNIT ASSY ,HEADLAMP ,LH (LED)	MTG BROKEN	3,455.00	2,637.59
1	HEAD LAMP PANEL (LH)	NOT NECESSARY	240.10	-
1	TOP PANEL CENTRE	NOT NECESSARY	364.98	-
1	TOP PANEL SIDE	NOT NECESSARY	145.90	-
1	FENDER SUB-ASSY ,FRONT LH	DENTED	945.30	945.30
1	FRONT FENDER SHIELD	DEFORMED	38.00	38.00
1	FRONT FENDER SHIELD CLIP	NECESSARY	14.90	14.90
1	FRONT FENDER HYBRID EMBLEM LH	NECESSARY	86.50	86.50
1	BRACKET ,FRONT SIDE PANEL ,LH	NOT NECESSARY	86.30	-
1	FRONT WHEEL RIM	CUT	1,570.55	1,555.00
1	FRONT WHEEL HUB BEARING	DAMAGED	560.10	560.10
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	637.50	637.50
1	FRONT SHOCK ABSORBER (LH)	DISTORTED	401.80	401.80
1	ABSORBER TOP MOUNTING	NOT NECESSARY	196.20	-
1	FRONT DRIVE SHAFT (LH)	NOT NECESSARY	1,764.00	-
1	LINK ASSY ,FRONT STABILIZER ,LH	NOT NECESSARY	199.00	-
1	KNUCKLE STEERING ,LH	DISTORTED	580.80	580.80
1	JOINT ASSY ,LOWER BALL ,FRONT (LH)	NOT NECESSARY	199.98	-
1	END SUB-ASSY ,TIE ROD ,LH	NOT NECESSARY	159.30	-
	LESS 20% DISCOUNT		-5,964.42	-
	LESS 25% DISCOUNT		-	-2,923.82
			23,857.69	8,771.47
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
1	REAR DOOR COMFORT & APPS STICKER (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	REAR TYRE (LH) (SN)	NOT NECESSARY	216.00	-

Report Ref No. CC6/CTI21004947/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TYRE (LH) (SN)	NOT NECESSARY	216.00	-
			637.00	155.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER GARNISH .		1,600.00	800.00
	SPRAY PAINTING CHARGE.		1,800.00	1,000.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR .		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS .	NOT NECESSARY	120.00	-
	REMOVE /REFIX REVERSE SENSOR .	NOT NECESSARY	120.00	-
	REMOVE/REFIX UNDERCARRIAGE (RR).	NOT NECESSARY	400.00	-
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	400.00	-
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	80.00	-
	TRANSFER OF DOOR MECHANISM FRONT .		80.00	60.00
	RE-SET FRT POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	TRANSFER OF DOOR MECHANISM REAR .		80.00	60.00
	RE-SET REAR POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		400.00	150.00
	RE-SET FRT ABS SYSTEM.	NOT NECESSARY	200.00	-
	REMOVE/REFIX RADIATOR .	NOT NECESSARY	90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	130.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
			7,000.00	2,430.00
GRAND TOTAL			31,494.69	11,356.47

RECOMMENDED COST OF REPAIRS			11,356.47
------------------------------------	--	--	------------------

Report Ref No. CC6/CTI21004947/Dea3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3422K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3422K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3422K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

