



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 5538D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DENTED	979.90	616.00
1	FRONT BUMPER BRACKET RIGHT	BROKEN	45.40	45.40
1	FRONT BUMPER BRACKET LEFT	BROKEN	45.40	45.40
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	68.00	-
1	LEFT HAND FOG LAMP COVER	NOT NECESSARY	68.00	-
1	RIGHT HAND FOG LAMP COVER	CUT	508.90	55.00
1	HEADLAMP (RH)	BROKEN	1,499.80	1,299.00
1	HEADLAMP RETAINER (RH)	BROKEN	55.90	55.90
1	FRONT BONNET	NOT NECESSARY	654.10	-
2	FRONT BONNET HINGES	NOT NECESSARY	64.00	-
1	FRONT GRILLE	BROKEN	577.90	320.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	874.50	-
1	FRONT RIGHT FOG LAMP	NOT NECESSARY	508.90	-
1	FRONT LEFT FOG LAMP	NOT NECESSARY	508.90	-
	LESS 20% DISCOUNT		-1,291.92	-487.34
			5,167.68	1,949.36
<u>LABOUR</u>				
	TO FIX & DISMANTLE AND REMOVE DAMAGED FRONTAL PORTIONS; AFFECTED DAMAGED PORTION.		800.00	200.00
	TO APPLY ANTI RUST COAT AND AFFECTED AREAS. (NPA)	NOT NECESSARY	-	-
	TO CHECK WIRING.		180.00	30.00
	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT. (NPA)	NOT NECESSARY	-	-
	SPRAY PAINTING FOR FRONTAL PORTIONS AFFECTED PARTS.		1,000.00	200.00
	REFOCUSING OF THE FRONT HEADLAMP.		180.00	30.00
	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE.	NOT NECESSARY	120.00	-
	3D WHEEL ALIGNMENT. (NPA)	NOT NECESSARY	-	-

Report Ref No. CS/INC21004950/Evf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY WATERPROOFING SEALER ON END PANELS.	NOT NECESSARY	129.00	-
			2,409.00	460.00
GRAND TOTAL			7,576.68	2,409.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,950.00

Report Ref No. CS/INC21004950/Evf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.