

ASS. REC. BY:

Steve

REF:

CS/INC 21904950/GVF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Turn Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLG 55380

Yr Regn:

4/10/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CIVIC

c.c

1498

Colour:

Silver

A/C:

Insured / Std / NI / N

Sp. Reading

119320

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

MRHFC1660GT000185

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brakes: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / OKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

8/4/21

D.O.A.

20/4/21

Survey held at

Auto Mega

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MIV-79K

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

: Prices

: Others

TOTAL

Pop Form:

Lump Sum / B.B. /

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SLG5538D
Chassis No:
Engine No:

Report No :
Date : 19.04.2021

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front Bumper	Damaged	\$ 979.90	\$ 881.91
2	1	Front Bumper Bracket Right	Necessary	\$ 45.40	\$ 40.86
3	1	Front Bumper Bracket Left	Necessary	\$ 45.40	\$ 40.86
4	1	Front Bumper Centre Grille	Scratches	\$ 68.00	\$ 61.20
5	1	Left Hand Fog Lamp Cover	Dislodge/Broken	\$ 68.00	\$ 61.20
6	1	Right Hand Fog Lamp Cover	Dislodge/Broken	\$ 508.90	\$ 458.01
7	1	Left Headlamp (CR4)	Scratches/Damaged	\$ 1,499.80	\$ 1,349.82
8	1	Left Headlamp Retainer (CR4)	Necessary	\$ 55.90	\$ 50.31
9	1	Front Bonnet	Misaligned	\$ 654.10	\$ 588.69
10	2	Front Bonnet Hinges	Necessary	\$ 64.00	\$ 57.60
11	1	Front Reinforcement	Impacted	\$ 577.90	\$ 520.11
12	1	Front Support Panel	Impacted	\$ 874.50	\$ 787.05
13	1	Front Right Fog Lamp	Impacted	\$ 508.90	\$ 458.01
14	1	Front Left Fog Lamp	Impacted	\$ 508.90	\$ 458.01
				\$ 6,459.60	\$ 5,167.68

Total (Parts): \$ 6,459.60 -20% \$ 5,167.68

Labour Charges

26	To fix & dismantle and remove damaged Frontal Portions; affected damaged portion.	\$ 800.00	200
27	To apply anti rust coat and affected areas	\$ -	X
28	To check wiring	\$ 180.00	30
29	Welding and cutting of affected panels, including chassis alignment.	\$ -	X
30	Spray painting for Frontal Portions affected parts	\$ 1,000.00	200
31	Refocusing of the front headlamp	\$ 180.00	30
32	Diagnose ECU system and reset error code.	\$ 120.00	X
33	3D Wheel Alignment	\$ -	X
34	To Apply Waterproofing sealer on End Panels	\$ 129.00	X
		Total Labour: \$ 2,409.00	

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 7,576.68

Less 20% \$ 6,061.34

AMM PTE LTD

Page 2 of 3

Stew CLKK

NR PL

20/4/21, 4.00pm

L/S

My AL sy

3 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: