

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SLG5538D
Chassis No:
Engine No:

Report No :
Date : 19.04.2021

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front Bumper	Damaged 616 ✓	\$ 979.90	\$ 881.91
2	1	Front Bumper Bracket Right	Necessary	\$ 45.40	\$ 40.86
3	1	Front Bumper Bracket Left	Necessary	\$ 45.40	\$ 40.86
4	1	Front Bumper Centre Grille	Scratches	\$ 68.00	\$ 61.20
5	1	Left Hand Fog Lamp Cover	Dislodge/Broken	\$ 68.00	\$ 61.20
6	1	Right Hand Fog Lamp Cover	Dislodge/Broken SS ✓	\$ 508.90	\$ 458.01
7	1	Left Headlamp (RH)	Scratches/Damaged 1249 ✓	\$ 1,499.80	\$ 1,349.82
8	1	Left Headlamp Retainer (RH)	Necessary	\$ 55.90	\$ 50.31
9	1	Front Bonnet	Misaligned	\$ 654.10	\$ 588.69
10	2	Front Bonnet Hinges	Necessary	\$ 64.00	\$ 57.60
11	1	Front Reinforcement grille	Impacted 320 ✓	\$ 577.90	\$ 520.11
12	1	Front Support Panel	Impacted	\$ 874.50	\$ 787.05
13	1	Front Right Fog Lamp	Impacted	\$ 508.90	\$ 458.01
14	1	Front Left Fog Lamp	Impacted	\$ 508.90	\$ 458.01
				\$ 6,459.60	\$ 5,167.68

Total (Parts): \$ 6,459.60 -20% \$ 5,167.68

Labour Charges

26	To fix & dismantle and remove damaged Frontal Portions; affected damaged portion.	\$ 800.00
27	To apply anti rust coat and affected areas	\$ - X
28	To check wiring	\$ 180.00
29	Welding and cutting of affected panels, including chassis alignment.	\$ - X
30	Spray painting for Frontal Portions affected parts	\$ 1,000.00
31	Refocusing of the front headlamp	\$ 180.00
32	Diagnose ECU system and reset error code.	\$ 120.00
33	3D Wheel Alignment	\$ - X
34	To Apply Waterproofing sealer on End Panels	\$ 129.00
Total Labour:		\$ 2,409.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 7,576.68

Less 20% \$ 6,061.34

Page 2 of 3

AMM PTE LTD

Steve CLKK

MM PL

20/4/21, 4.00pm

L/S

My AL sy

3 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2436-79
-20%
1949-36

= 2409.36
L/S - 1927.48
= 1950