ASS. REC. BY: Steve | NEF: CS/MSG 21,004959/EVF3 ASSIGNMENT Veh No: USU 96/J/4 Yr Regn: 17/12
Type: Myary M. Cycle / Bus / Van J Lorry / Taxl / Prime Mover / From: Dale: Estimated Cost: OD (TP) WS/TP RES/ OD RES/ EVA/INV/ MV Toph Hace To Inspect Vehicle No: Make: at Workshop m/s T/Radio; Insured / Std / NI / N Sp.Reading Insured: SLL 9063D Eng/No: KO4 2010236655 Policy No. 30001722266 C/No: Gen. Cond: Good / Eair / Poor / Burnt Claims No. <u>256144</u> Sleering: Inded / Jammed / Leaked / Burnt or Excess: Sum Insured: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: NII / S/RIM / STO A/BIM or Make of Veh: Tyre Size: (Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / Remark: The veh had commenced its GT190161 TOYO / YOKO or repair at the time of inspection. Rear Fron Bal. or Market Value: R/Bal. R/Bal. Consistent?: Yes or No IDAC Accident Roort: UBal. IJBal. Consistent?: Yes or No GIA / PR Seen: days Est. Repairs: Think 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages : Frt / Rear) / O/S / N/S / U/C / Rooftop or CA I REV I REP. I 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision Person Contacted: Action / Instruction Date / Time Steve call workshop, vehicle has not send in for repair Submit preli report-revised fig \$3715.25, check items \$348 7/7/21 Days Of Repair: 3 rate/Time, File Pass to? : Prell. Report Survey Fee: Resurvey No. of Trip: ; Final Report Transportation: Oate/Time, File Return to? _S + RS.__SI : Site Insp (\$ Add Fee: , 7/7/21-Typist Friolis : Interview (\$ Cithers ுழை**ச**்ரைக் : Merimen : Tech. Inva (8 Weetend (\$ i, early Sean / LED: Co TOTAL

Think One Autocare Pte Ltd No.60 Jalan Lam Huat #02-32 Carros

No.60 Jalan Lam Huat #02-32 Carros Centre Singapore 737869 9793 8471 much		
Singapore 737869 9793 8472 mich		
17886 (LNN) 111		
C201 (C12		
Store Chen @ 1KKouts. com 21/4/21, 1-09h		
GRC0679 A TOYOTA HILLON		
No Qty PARTICULAR J dys , DATE	20.04.2021	
1 1 TAIL GATE / M		UNT S\$
2 1 TAIL GATE AUTO LOCK SENSOR X NN	4	2,062.00 855.00
3 1 TAIL GATE (LOGO) EMBLEM		165.00
4 1 REAR BUMPÈR 🖊 🎊		1,260.00
5 1 REAR BUMPER FOOT STEP ?		221.00
6 2 REAR BUMPER SIDE RETAINER 7 121.50	10	243.00
	\$ 4	,806.00
LESS 25%		,201.50
	\$ 3	3,604.50
No Qty PARTICULAR SPECAIL NETT	AMO	UNT S\$
1 1 70 KM/H STICKER / MC	20	25.00
2 1 REVERSE SENSOR — OK		200.00
2 I REVERSE SENSOR > 0A	\$	225.00
A A DOVID O MICCELL ANICOLIC.		
LABOUR & MISCELLANEOUS:		800.00
To remove damaged body parts with all necessary components/attach-	411	000.00
ments apply hot-works where necessary repair, reshape body dented	•	
panels in accordance with factory specifications replace new parts refit		
and align into position refit all necessary components/attachments		
	Ota	800.00
To spray paint replaced/repaired body parts inclusive of preparatory	250	000.00
works and painting materials		
	50	150.00
To transfer tail gate components with all necessary attachments	90	130.00
	.00	150.00
To remove, refix rear windscreen glass and water test	175	130.00
	70	100.00
To install reverse sensor and test funtion	00	100.00
	70	100.00
6 Apply anti rust solution on affected areas	-6 7	100.00
LKK Auto Consultants hence notify	\$ 4	.,100.00
the Renairer of the following:		
To resurvey before/after spray painting		
To display damaged part(s) during resurvey Parts prices are subject to confirmation		
• Third party survey is on a "Without Prejudice" Cas 5		
• No (legal mode cation(s) is allowed		
Supplementary item(s) must be resurveyed at is subject to final approval from Insurance Company is subject to final approval from Insurance Company		
Acknowledged by Repairer		
Acknowledged by Repairer Signature:		
Date:		



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate Delicy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

A second of the Police for Investigation.

5. Any false reporting may be referred to the Police for investigation.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 20/04/2021 14:43 (SGT) Date of Accident 17/04/2021 11:45 (SGT) **Exact Location of Accident** 1 Woodlands Street 13, Singapore 738597 Additional Location Information blk 185 multi carpark Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

GBG9678A

Toyota

INSURED/POLICYHOLDER Is company? Name Of Registered Owner THINK ONE LEASING PTE LTD Company Reg No 2XXXXX609M **Email Address** RAJ@TOL.COM.SG Mobile Phone No (Phone) +65-96788288 Alternative Phone No (Office) +65-6553300

VEHICLE PARTICULARS

Manufacturer

Vehicle Registration Number

Hiace Exact purpose for which vehicle was being used at time of accident **Employment** Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Commercial vehicle Transmission Manual 2500

INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd Type of Coverage ThirdPartyFireTheft Fleet Policy Yes Policy Number 20-ML000183-R00 Cover Note Number

DRIVER

THAM LEE MENG NRIC No SXXXX024C

Date Of Birth 29/05/1985 Occupation Outdoor Date Of Driving Pass 15/02/2005 Driving experience 16 YEARS AND 2 MONTHS Gender Male Mobile Number (Phone) +65-90701736 Alt. Phone Number **Email Address** RAJ@TOL.COM.SG Address **BLK 517 WOODLANDS DRIVE 14** Address complement #02-255 Postcode 730518 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collided into Parked Vehicle Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 17.04.2021 AT ABOUT 11:45HRS MY VEHICLE BEARING NUMBER GBG9678A WAS PARKED AT THIRD FLOOR PARKING LOT OF MULTI CARPARK WLW185 3AFLOOR WHILE VEHICLE NUMBER SLL9063D DRIVE DOWN FROM UPPER FLOOR COLLIDED ON MY REAR PORTION CAUSE DAMAGED. ATTACHMENT(S)

記録: DETAILS OF OTHER VEHICLE PROPERTY 北


Yes

No

No

Vehicle Registration Number	SLL9063D
Vehicle Manufacturer	Toyota
Vehicle Model	Corolla
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	WONG PE

Private hire
WONG PENG YIN
SXXXX494B



Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?