



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref: CS/MSM21004968/R1tf3e2

C/O: MSM INTERNATIONAL ADJUSTERS
(SINGAPORE) PTE LTD
141 CECIL STREET #07-02
TUNG ANN ASSOCIATION BUILDING
SINGAPORE 069541

Date: 10/06/2021

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLU 4311Z
Policy No.	20/21/21/EC00/002240	Coverage (\$)	0.00
Claim No.	SIN1000461	Excess (\$)	0.00
Assign From	LIN JUN BING	Assign Date	20/04/2021

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 218i CONVERTIBLE	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA2M12050VB68283	Colour	WHITE
Odometer	49927 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	PIRELLI	6 mm
L/H Front Tyre	225/45 R17	PIRELLI	6 mm
R/H Rear Tyre	225/45 R17	PIRELLI	6 mm
L/H Rear Tyre	225/45 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/04/2021	Inspection Date	20/04/2021
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
--	-----------------------