



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD C/O: MSM INTERNATIONAL ADJUSTERS (SINGAPORE) PTE LTD 141 CECIL STREET #07-02 TUNG ANN ASSOCIATION BUILDING SINGAPORE 069541			Ref: CS/MSM21004968/R1tf3e2 Date: 10/06/2021	Code: LPC2
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLU 4311Z	
Policy No.	20/21/21/EC00/002240	Coverage (\$)	0.00	
Claim No.	SIN1000461	Excess (\$)	0.00	
Assign From	LIN JUN BING	Assign Date	20/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 218I CONVERTIBLE	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA2M12050VB68283	Colour	WHITE	
Odometer	49927 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	PIRELLI	6 mm	
L/H Front Tyre	225/45 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/04/2021	Inspection Date	20/04/2021	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	