

Supplementary Parts to be replaced:		Price (nett)	
ANGULAR CONTACT BALL BEARING R	? X	\$ 156.60	no photo
CABLE CLIP TRIPLE @ \$2.95/pc	rec / 4 pcs	\$ 11.80	rec / ✓
ALLOY RIM 7.5X17 V SPK 725	✓	\$ 930.80	Cut / ✓
BLIND RIVET NUT (M8) @ \$3.85/pc	4 pcs	\$ 15.40	rec / ✓
(S/L) SOUND INSULATION WINDSHIELD ?	✓	\$ 102.65	no photo nec ✓
BATTERY CABLE (PLUS POLE)	✓	\$ 296.80	rec / ✓
(DG) RH BELT TENSIONER	✓	\$ 273.00	Act / ✓
Total Parts :		\$6,523.40	
Supplementary Labour to be charged:			
1) To replace rear right support structure, right top side member including to pull and straighten before cutting and to knock out dented area caused by the accident		\$3,400.00	? 3230
2) To replace fuel tank including to extract fuel and conduct Checks for leak		\$ 531.00	? 504
3) To mount vehicle on Car O Liner to facilitate re-alignment of body / chassis according to BMW specification		\$2,950.00	? 2803
4) To replace battery positive cable, perform high current test And charge up battery		\$ 531.00	? 504
5) To replace right seat belt tensioner including to reset and check for proper function		\$ 531.00	? 426
Total Labour :		\$7,943.00	
Total Supplementary Parts + Labour		\$14,466.40	
GST 7%		\$ 1,012.65	
Total		\$15,479.05	

BMW Dealer

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motored)



## SERVICE TAX INVOICE

Repair Order No.	<b>b1 1552415</b>	Page No.	<b>1 of 5</b>	Download BMW Performance SG Mobile App Today. 
Date In	<b>23/04/2021</b>	Invoice Number	<b>2405028 / WSB</b>	
Motor Claim Advisor	<b>Han Kwan Yong</b>	Invoice Date	<b>14/07/2021</b>	
		Payment Term	<b>Cash</b>	
		Invoice By	<b>Han Kwan Yong</b>	

- CUSTOMER INFORMATION - <b>Really Octstella Tanla Ho</b> 42 Penaga Place Singapore 757160	- INVOICE TO - <b>40000</b> <b>Cash Sales - Service</b> <b>Singapore</b>
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLU4311Z</b>	<b>WBA2M12050VB68283</b>	<b>30/11/2017</b>	<b>218IA-C</b>	<b>49927</b>

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
1	T001	To tow accident vehicle to PML workshop.	1.00		✓ 150.00
	32306791332	(DG) AIRBAG MODULE DRIVER'S SIDE	1.00		✓ 1,407.30
	61129253111	BATTERY CABLE (PLUS POLE)	1.00		✓ 296.80
	51457943495	INSTRUMENT PANEL WITH DEC. STITCHIN	1.00		✓ 1,962.50
	07147201307	EXPANDING NUT <i>ne /</i>	1.00		(A) 0.95
	07149213164	HEX BOLT <i>ne /</i>	1.00		(A) 1.50
	36116879186	ALLOY RIM 7.5X17 V SPK 725	1.00		✓ 930.80
	33326792554	PUSH ROD <i>ne /</i>	1.00		(A) 56.25
	51757241834	RH SIDE UNDERBODY PANELLING	1.00		✓ 103.95
	33306861221	TORX BOLT ISA M12X35 <i>ne /</i>	5.00		(A) 36.75
	31106858433	HEX BOLT WITH WASHER M10X22 <i>ne /</i>	2.00		3007 10.00
	72117259388	(DG) RH BELT TENSIONER	1.00		✓ 273.00
	33406799223	COLLAR NUT <i>ne /</i>	1.00		(A) 9.85
	07147201307	EXPANDING NUT <i>ne /</i>	2.00		(A) 1.90
	07149213164	HEX BOLT <i>ne /</i>	2.00		(A) 3.00
	51317240639	FRT W/SCREEN W/RAIN SENSOR	1.00		✓ 684.50
	51317240671	FRT W/SCREEN MOULDING	1.00		✓ 53.80
	51317288462	BUMP STOP	5.00		✓ 16.00
	83192289285	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2.00		✓ 263.10
	83199407777	(DG/SL)ADHESIVE PRIMER VP 206 (30ML)	1.00		✓ 27.85
	83192211217	(DG) CLEANER R1 (100ML)	1.00		✓ 26.15
	51487458549	(S/L)SOUND INSULATION WINDSHIELD L=	1.00		✓ 102.65
	16117294604	PLASTIC FUEL TANK <i>scr /</i>	1.00		(A) 1,331.55
	16137244150	ACTIVATED CHARCOAL FILTER <i>ca /</i>	1.00		(A) 188.55
	33306793892	TORX SCREW WITH COLLAR M12X110 <i>ne /</i>	4.00		(A) 48.40
	33316794866	STOPPER, REAR <i>ne /</i>	1.00		(A) 30.35
	33316851656	REAR AXLE CARRIER	1.00		✓ 1,776.40
	33326792525	TRAILING ARM WITH RUBBER MOUNT	1.00		✓ 112.15
	33326792533	TRACK STRUT WITH RUBBER MOUNT	1.00		✓ 128.20
	33326792540	RH GUIDING SUSPENS. LINK W RUBBER M	1.00		✓ 272.40
	33326792544	RH CONTROL ARM W/RUBBER BUSHING	1.00		✓ 320.45



BMW Dealer

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)


303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kembangan Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorsad)



## SERVICE TAX INVOICE

Repair Order No. **b1 1552415**Page No. **2 of 5**Download BMW Performance  
SG Mobile App Today.Date In **23/04/2021**Invoice Number **2405028 / WSB**Invoice Date **14/07/2021**Motor Claim Advisor **Han Kwan Yong**Payment Term **Cash**Invoice By **Han Kwan Yong**

33326796138	COVERING RH	1.00	✓	55.00
33326867540	ROLL OVER STRUT WITH RUBBER MOUNT	1.00	✓	352.50
33406799223	COLLAR NUT <i>am</i>	1.00		9.85
34526791926	CABLE CLIP TRIPLE	4.00	✓	11.80
41132291403	BLIND RIVET NUT (M8)	4.00	✓	15.40
51757241838	EXTENSION FLOORPAN COVER SIDE RH <i>sent</i>	1.00		88.05
72129205197	(DG) AIRBAG FOR FRONT PASSENGER	1.00	✓	1,267.30
07119906489	HEX BOLT W WASHER M12X1.5X67-10.9 <i>am</i>	4.00		18.00
07149213164	HEX BOLT <i>am</i>	20.00		30.00
31106760122	HEX BOLT M8X30 <i>am</i>	4.00		17.20
33326796225	TORX SCREW WITH COLLAR M10X30 <i>am</i>	4.00		21.20
	To replace rear right tyre - Pirelli CP7 225/45 R17 - <i>cut</i>	0.00		268.75

Sub-Total : 12,782.10

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
2	BP	To replace right under body panelling including to knock our floor panel and dented area caused by the accident	1.00	✓	✓ 850.00
	41007299550	RH TOP SIDE MEMBER	1.00		(A) 454.05

Sub-Total : 1,304.05

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
3	sp	To respray under floor panel and spray thermostat	1.00	✓	✓ 426.00
					Sub-Total : 426.00

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
4	33003	To remove and install rear suspension, rear axle and control system for inspection and replace damaged parts.	1.00	✓	✓ 2,522.00
	3M SOLAR FILM	3M S/F CRYSTALLINE FRONT WINDSCREEN <i>am</i>	1.00		(A) 420.56

Sub-Total : 2,942.56

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
5	51009	To replace front dashboard panel and conduct check for proper function.	1.00	✓	✓ 757.00

Sub-Total : 757.00

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
6	32004	To replace steering wheel bag including reset and check air bag system for function.	1.00	(A)	✓ 504.00

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax 64796601 (AfterSales)  
64796624 (Motorrad)



## SERVICE TAX INVOICE

Repair Order No. **b1 1552415**Page No. **4 of 5**Download BMW Performance  
SG Mobile App Today.Date In **23/04/2021**Invoice Number **2405028 / WSB**Invoice Date **14/07/2021**Motor Claim Advisor **Han Kwan Yong**Payment Term **Cash**Invoice By **Han Kwan Yong**

			Sub-Total :	0.00	
JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
17	51617323344	RH PULL ROD <i>lt</i>	1.00		198.65
	16127351133	SCAVENGE AIR LINE <i>cut</i>	1.00		105.50
	41007409774	RH SUPPORT STRUCTURE <i>bt</i>	1.00		1,171.35
	16117426684	RH TENSION STRAP <i>lt</i>	1.00		55.35
	51717424020	REAR RH WHEEL HOUSING COVER <i>scr</i>	1.00		132.40

Sub-Total : 1,663.25

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
27	4199000	To replace rear right support, right top side member including pulling and panel beating on lower damaged panel.	1.00	<i>s1</i>	3,230.00 ✓

Sub-Total : 3,230.00

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
29	1611535	Replacing fuel tank including to extract and conduct checks for leak	1.00	<i>s1</i>	504.00 ✓

Sub-Total : 504.00

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
36	6112502	Replacing positive battery cable, perform high current test and charge up battery	1.00	<i>s1</i>	504.00 ✓

Sub-Total : 504.00

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
40	5199000	Mount car on car o liner bench to facilitate re-alignment of body/chassis according to BMW specification	1.00	<i>s1</i>	2,803.00 ✓

Sub-Total : 2,803.00

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
46	9999000	Painting under floor panel, putty work and thermostat	1.00	<i>(a)</i>	426.00 ✓

Sub-Total : 426.00

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
51	3400550	Bleeding brake system with DSC and check for leak	1.00	<i>(A)</i>	273.00 ✓

Sub-Total : 273.00



## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motormat)



## SERVICE TAX INVOICE

Repair Order No. **b1 1552415** Page No. **3 of 5**  
Date In **23/04/2021** Invoice Number **2405028 / WSB**  
Motor Claim Advisor **Han Kwan Yong** Invoice Date **14/07/2021**  
Payment Term **Cash**  
Invoice By **Han Kwan Yong**

Download BMW Performance  
SG Mobile App Today.



		Sub-Total :		504.00
JOB CODE	DESCRIPTION	UNITS	DISC %	NETT
7 72007	To replace front dashboard passenger air bag including reset and conduct check for proper function.	1.00	✓	✓ 504.00
		Sub-Total :		504.00
JOB CODE	DESCRIPTION	UNITS	DISC %	NETT
9 51002	To replace front windscreen glass.	1.00	✓	✓ 676.00
		Sub-Total :		676.00
JOB CODE	DESCRIPTION	UNITS	DISC %	NETT
10 51005	To remove and install IU unit bracket.	1.00	✓	✓ 31.00
33326760668	HEX NUT WITH FLANGE	4.00	(A)	10.00
		Sub-Total :		41.00
JOB CODE	DESCRIPTION	UNITS	DISC %	NETT
11 51006	To conduct water leak tests.	1.00	✓	✓ 75.00
		Sub-Total :		75.00
JOB CODE	DESCRIPTION	UNITS	DISC %	NETT
14 61011	To check electrical wiring system and lighting including reset and check air bag for proper function.	1.00	✓	✓ 280.00
61337400705	HORN HIGH PITCH ?	1.00	cra	81.30
61337400706	HORN LOW PITCH ?	1.00	cra	81.30
		Sub-Total :		442.60
JOB CODE	DESCRIPTION	UNITS	DISC %	NETT
15 ps10	Sundries	1.00	✓	✓ 150.00
		Sub-Total :		150.00
JOB CODE	DESCRIPTION	UNITS	DISC %	NETT
16 OCLA1WPN	ACCIDENT REPAIR: T/P DIRECT CLAIM	0.00		0.00
		SURVEYOR'S NAME: MR RASUL SURVEY ON: 20/04/21 (11:00 AM)		
		A/R BY: OWNER MS TANIA HO A/R ON: 21/04/21 (17:28 PM)		
		DATE OF ACCIDENT: 11/04/2021		

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 1974015399W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motors)



## SERVICE TAX INVOICE

Repair Order No. **b1 1552415**Page No. **5 of 5**Download BMW Performance  
SG Mobile App Today.Date In **23/04/2021**Invoice Number **2405028 / WSB**Invoice Date **14/07/2021**Motor Claim Advisor **Han Kwan Yong**Payment Term **Cash**Invoice By **Han Kwan Yong**

JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
52	7211570	Replacing front lower belt on driver's seat including to reset and check for function	1.00	s1	392.00
Sub-Total :					392.00
JOB	CODE	DESCRIPTION	UNITS	DISC %	NETT
53	9000115	Topping up petrol (full tank) @ \$125.64 <i>nu</i> (a)	1.00		117.42
Sub-Total :					117.42

Labour Charges	:	<b>15,443.17</b>	Total Labour & Parts Charges	:	<b>S\$ 30,516.98</b>
Parts Charges	:	<b>15,073.81</b>	Less Insurance Excess	:	<b>S\$ 0.00</b>
Lubricant/Misc	:	<b>0.00</b>	Invoice Total Amount Exclude GST	:	<b>S\$ 30,516.98</b>
			GST @ 7%	:	<b>S\$ 2,136.19</b>
			Invoice Total Amount Include GST	:	<b>S\$ 32,653.17</b>
			Less Deposit/Voucher	:	<b>S\$ 0.00</b>

Computer generated invoice. No signature is required.

Amount Payable Include GST: : **S\$ 32,653.17**

With effect from 1 Sep 2021, all payments can only be made via BMW Contactless Payment Link, Bank Transfer, NETS, PayNow and Credit Card (Visa, Masters, Amex, Google/Apple Pay and PayWave). Visit <https://pml-bmw.com.sg/bmw-convenience-360/> or contact 1800-2255-269 for more information on the full list of accepted cashless payment methods.

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.

