	Price (nett)	
Supplementary Parts to be replaced:	\$ 156.60	
ANGULAR CONTACT BALL BEARING R  CABLE CLIP TRIPLE  @ \$2.95/pc 2 rec / 4 pcs		
	\$ 930.80	1
ALLOY RIM 7.5X17 V SPK 725  BLIND RIVET NUT (M8) @ \$3.85/pc 4 pcs	\$ 15.40	
BLIND RIVET NUT (M8) @ \$3.85/pc 4 pcs (S/L)SOUND INSULATION WINDSHIELD?	\$ 102.65	
	\$ 296.80	100000
BATTERY CABLE (PLUS POLE)	\$ 273.00	1600
(DG) RH BELT TENSIONER  Total Parts:	\$6,523.40	
Supplementary Labour to be charged:		
1) To replace rear right support structure, right top side	\$3,400.00	
member including to pull and straighten before cutting		
and to knock out dented area caused by the accident		
and to knock out defined theu educate of the decident		
2) To replace fuel tank including to extract fuel and conduct	\$ 531.00	
Checks for leak		
3) To mount vehicle on Car O Liner to facilitate re-alignment	\$2,950.00	
of body / chassis according to BMW specification		
4) To replace battery positive cable, perform high current test	\$ 531.00	
And charge up battery		
To replace right seat belt tensioner including to reset and	\$ 531.00	
check for proper function		
Total Labour :	\$7,943,00	
otal Supplementary Parts + Labour	\$14,466.4	
ST 7%		
	\$ 1,012.6	
lotal	315,479.0	