BANW Deale

0

Performance Motors Limited

A Sime Derby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770 280, Kampong Arang Road East Const Centre Singapore 438180 115, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax: 64796601 (AfterSales)

Bestongance Moseys Limited



SERVICE TAX INVOICE

Repair Order No. b1 1552415

Page No. 1 of 5

Invoice Number 2405028 / WSB

Invoice Date 14/07/2021

Payment Term Cash

Invoice By Han Kwan Yong

- CUSTOMER INFORMATION -Really Octstella Tania Ho

42 Penaga Place

- INVOICE TO -Cash Sales - Service

Singapore

Singapore 757160

REGN. NO. SLU4311Z		CHASSIS NO. REGN. DATE WBA2H12050VB68283 30/11/2017	MODEL 218IA-C	MILEAGE 49927
308 0	ODE	DESCRIPTION	UNITS DISC	% NETT
nati		To tow accident vehicle to PML workshop.	1.00	√ 150.0
	001 2306791332	(DG) AIRBAG MODULE DRIVER'S SIDE	1.00	1,407.3
	1129253111	BATTERY CABLE (PLUS POLE)	1.00	296.8
	1457943495	INSTRUMENT PANEL WITH DEC. STITCHIN	1.00	1,962.5
TTOLS.	7147201307	EXPANDING NUT MA	1.00	(A)o.
20	7149213164	HEX BOLT AV /	1.00	(A) 1.
	116879186	ALLOY RJM 7.5X17 V SPK 725	1.00	J 930.
100	326792554	PUSH ROD NA /	1.00	(A) 56
	757241834	RH SIDE UNDERBODY PANELLING	1.00	103
MINT A	306861221	TORX BOLT ISA M12X35 NA	5.00	(A) 36
	106858433	HEX BOLT WITH WASHER M10X22 N	2.00	3000 10
	117259388	(DG) RH BELT TENSIONER	1.00	V273
	406799223	COLLAR NUT NO.	1.00 and the party lates are selected at 1.00	(A) ⁹
- 33	147201307	EXPANDING NUT N	2.00	(A)
	149213164	HEX BOLT NU	2.00	(A)
	317240639	FRT W/SCREEN W/RAIN SENSOR	1.00	✓ 68
	317240671	FRT W/SCREEN MOULDING	1.00	, 5
	317288462	BUMP STOP	5.00	1
83	192289285	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2.00	√ 26
83	199407777	(DG/SL)ADHESIVE PRIMER VP 206 (30ML	1.00	MATE 14 5 1 2
83	192211217	(DG) CLEANER R1 (100ML)	1.00	√ 2
51	487458549	(S/L)SOUND INSULATION WINDSHIELD L=	1.00	10
16	117294604	PLASTIC FUEL TANK SUL	1.00	(A) 1,33
10	5137244150	ACTIVATED CHARCOAL FILTER CA	1.00	(A) 18
3:	3306793892	TORX SCREW WITH COLLAR M12X110	4.00	(A)4
3	3316794866	STOPPER, REAR M	1.00	(A) 3
3	3316851656	REAR AXLE CARRIER	1.00	V 1,770
3	3326792525	TRAILING ARM WITH RUBBER MOUNT	1.00	✓ ✓ 112
3	3326792533	TRACK STRUT WITH RUBBER MOUNT	1.00	V 128
3	3326792540	RH GUIDING SUSPENS, LINK W RUBBER M	1.00	● √277
3	3326792544	RH CONTROL ARM W/RUBBER BUSHING	1.00	√ 320

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770 280, Kempong Arang Road East Coast Centre Singapore 438180 Fax. 63449773 315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax 64796601 (AfterSales) 64796624 (Motornad)

Performance Motors Limited



SERVICE TAX INVOICE

Repair Order No. Date In Motor Claim Advisor	b1 1552415 23/04/2021 Han Kavan Yong	Page No. Invoice Number Invoice Date Payment Term Invoice By	2 of 5 2405028 / WSB 14/07/2021 Cash Han Kwan Yong	CHECKS CONTRACT	Cownload BMW Performance SC Mobile App Today.
3332679613	38 COVERING RH			1.00	/55.00
3332686754	0 ROLL OVER STRUT WITH RU	JBBER MOUNT		1.00	352.50
3340679922	3 COLLAR NUT AM			1.00	9.85
3452679192	6 CABLE CLIP TRIPLE			4.00	● √11.80
4113229140	3 BLIND RIVET NUT (M8)			4.00	V 15.40
5175724183	8 EXTENSION FLOORPAN COV	ER SIDE RH SUN		1.00	88.05
7212920519	7 (DG) AIRBAG FOR FRONT PA	SSENGER		1.00	1,267.30
0711990648	9 HEX BOLT W WASHER M12X	1.5X67-10.9		4.00	18.00
0714921316	4 HEX BOLT M			20.00	30.00
3110676012	2 HEX BOLT MBX30 A	,		4.00	17.20
3332679622	TORX SCREW WITH COLLAR	M10X30 ~	. John Wall	4.00	21.20
	To replace rear right tyre - Pl	relli CP7 225/45 R17 - C	41	0.00	268.75
			(127)	Sub-To	tal: 12,782.10
OB CODE	DESCRIPTION			UNITS DIS	C% NETT
		THE RESERVE OF THE PARTY OF			
ВР	To replace right under boby ;	panelling including to knoc	k	1.00	850.00
	our floor panel and	dented area cause	ed by the accident		A 181
41007299550	RH TOP SIDE MEMBER			1.00	(A) 454.05
				COLUMN TO STATE OF THE	1 204 05
				Sub-To	tal: 1,304.05
OB CODE	DESCRIPTION	and the second	- NA ESCHARGE	UNITS DIS	SC % NETT
Assert					, estatstatet
sp	To respray under floor panel	and spray thermostat		1.00	426.00
				Sub-To	tal: 426.00
				10 TAN 101	ABILISTALS
OB CODE	DESCRIPTION		precou	UNITS DI	SC % NETT
-					Tadacce LC
33003	To remove and install rear sur			1.00	2,522.00
	control system for parts.	inspection and	replace damage	d	23 213 23 24 23
3M SOLAR FIL	THE REAL PROPERTY AND ADDRESS OF THE PARTY AND	WINDSCREEN NA	MOD RES STATEM	1.00	(A) 420.56
		THE PARTY OF THE P			(//) 420.50
				Sub-To	tal: 2,942.56
B CODE	DESCRIPTION			UNITS DI	SC % NETT
			No. of Concession, Name of Street, or other party of the Concession, Name of Street, or other party of the Concession, Name of		The same of the sa
51009	To replace front dashboard po	snel and conduct check for		1.00	/ / 757.00
NAME OF TAXABLE PARTY.	proper function.	The State of the S	THE REAL PROPERTY.	THURS IN CO.	V V /3/.00
	The state of the s			May of the little	
				Sub-To	tal: 757.00
OB CODE	DESCRIPTION		Shirts are a	UNITS DIS	SC % NETT
32004	To replace steering wheel bag		k air	1.00	(A) \square 504.00

Performance Motors Limited

A Sime Darty Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)
303, Alexandra Road
Sime Darty Performance Centre
Singapore 159941
Fax. 64747770
Fax. 634

Performance Motors Limited



SERVICE TAX INVOICE

Repair Order No. Date In Motor Claim Advisor	b1 1552415 23/04/2021 Han Kwan Yong	Page No. Invoice Number Invoice Date Payment Term Invoice By	4 of 5 2405028 / WSB 14/07/2021 Cash Han Kwan Yong	EDITOR OF THE PARTY OF THE PART	Download BMM Performance SG Mobile App Today.
20105	: lateT-due			Sub-Total	0.00
JOB CODE	DESCRIPTION	100		UNITS DISC	% 3000 NETT
17 51617323344 16127351133	RH PULL ROD H/ SCAVENGE AIR LINE CH/	WIND THE P. LEW.		1.00	198.65 105.50
41007409774 16117426684	RH SUPPORT STRUCTURE 6			1.00	1,171.35 55.35
51717424020	REAR RH WHEEL HOUSING CO	VER SUN		1.00	132.40
man V				Sub-Tota	1,663.25
OOB CODE	DESCRIPTION		A PARTY NAMED IN COLUMN	UNITS DISC	% NETT
7 4199000	To replace rear right support, ri			1.00 s1	3,230.00
				Sub-Tota	d: 3,230.00
OB CODE	DESCRIPTION			UNITS DISC	% NETT
1611535	Replacing fuel tank including to	extract and conduct che			s1 / 504.00
				Sub-Tota	al: 504.00
B CODE	DESCRIPTION		100	UNITS DISC	% NETT
6112502	Replacing positive battery cable, test and charge up bat		an despite pale surprise ton	1.00 s1	✓ ✓ 504.00
				Sub-Tota	al: 504.0
B CODE	DESCRIPTION			UNITS DISC	% NETT
5199000	Mount car on car o liner bench to body/chassis according			1.00 S1	2,803.00
				Sub-Tota	al: 2,803.0
B CODE	DESCRIPTION	non-		UNITS DISC	: % NETT
9999000	Painting under floor panel, putty	work and thermostat		1.00 (a	,
				Sub-Tota	d: 426.00
B CODE	DESCRIPTION	STANDER NO Y	British State of the State of t	UNITS DISC	% NETT
3400550	Bleeding brake system with DSC	and check for leak	RUN OF ASSESS OF	1.00	A) / 273.00
		Comment of the second		Sub-Tota	1: 273.00

BMW Dealer

Performance Motors Limited

A Sime Derby Motors Company
Co. Reg. No. 197401599W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)
303, Alexandra Road
Sime Derby Performance Centre
Singapore 159941
Fax. 64747770
Fax. 63

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773



SERVICE TAX INVOICE

Repair Order No. Date In Motor Claim Advisor	b1 1552415 23/04/2021 Han Kwan Yong	Page No. Invoice Number Invoice Date Payment Term Invoice By	3 of 5 2405028 / WSB 14/07/2021 Cash Han Kwan Yong		ad BMW Performance Nobile App Today.
100	; tarb-Total ;			Sub-Total:	504.00
JOB CODE	DESCRIPTION		A THE STATE OF	UNITS DISC %	BROO NETT
7 72007	To replace front dashboard reset and conduct of			Sub-Total:	504.00 504.00
ODE CODE	DESCRIPTION		1		
9 51002	To replace front windscreen	glass.		1.00	676.00
				Sub-Total :	676.00
OB CODE	DESCRIPTION			UNITS DISC %	NETT
10 51005 3332676060	To remove and install IU un	it bracket.	of his personal leave	1.00 4.00 Sub-Total :	(A) 10.00 41.00
OOB CODE	DESCRIPTION	Vindo to	and the barrens of prints	UNITS DISC %	ZEELEN NETT
51006	To conduct water leak tests			1.00 Sub-Total :	√ √ 75.00
				UNITS DISC %	NETT
OB CODE	DESCRIPTION	and a	V calles, medican hading value	CHAIS DESCRIPT	0111502
61011	To check electrical wiring sy reset and check at	stem and lighting including r bag for proper f	g 'unction.	egrand bi.00 fast	✓ ✓ ^{280.0}
613374007	05 HORN HIGH PITCH ?			1.00	cra 81.3
613374007	06 HORN LOW PITCH ?			Sub-Total :	442.6
				UNITS DISC %	NETT
JOB CODE	DESCRIPTION	801383111	SELECTION OF SECURITY	UNIIS DISC 40	/
15 ps 10	Sundries			1.00	150.00
				Sub-Total:	150.00
JOB CODE	DESCRIPTION	100000	Company from Street, Street, St.	UNITS DISC %	NETT
16 OCLA1WNP	SURVEYOR'S NAME:	MR RASUL SURVEY (ON: 20/04/21 (11:0		0.00

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fex. 63449773



SERVICE TAX INVOICE

Repair Order No.

b1 1552415

Page No.

5 of 5

Date In

23/04/2021

Motor Claim Advisor Han Kwan Yong

Invoice Number 2405028 / WSB

Invoice Date 14/07/2021

Payment Term Invoice By

Han Kwan Yong

Download BMW Performance SG Mobile App Today.



ЭОВ	CODE	DESCRIPTION	UNITS	DISC %	NETT
52	7211570	Replacing front lower belt on driver's seat including to reset and check for function	1.00	s1	/ 392.00
			Su	b-Total :	392.00
308	CODE	DESCRIPTION	UNITS	DISC %	NETT
53	9000115	Topping up petrol (full tank) @ \$125.64	a) 1.00		117.42
			Su	b-Total :	117.42

Computer generated invoice. No signature is required.			Amount Payable Include GST:			5\$	32,653.17
			Less Deposit/Voucher			5\$	0.00
			Invoice Total Amount Include GST		:	S\$	32,653.17
			GST @ 7%	:		S\$	2,136.19
Lubricant/Misc	1	0.00	Invoice Total Amount Exclude GST			5\$	30,516.98
Parts Charges		15,073.81	Less Insurance Excess			S\$	0.00
Labour Charges		15,443.17	Total Labour & Parts Charges		:	S\$	30,516.98

With effect from 1 Sep 2021, all payments can only be made via BMW Contactless Payment Link, Bank Transfer, NETS, PayNow and Credit Card (Visa, Masters, Amex, Google/Apple Pay and PayWave). Visit https://pml-benw.com.sq/bmw-convenience-360/ or contact 1800-2255-269 for more information on the full list of accepted cashless payment methods.

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debted on overdue amounts.

