



Rico 60 Auto Services Pte Ltd
 Blk 8 , Kaki Bukit Avenue 4 , #02-24
 Premier @ Kaki Bukit Singapore 415875
 Email: claims@rico60.com
 Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -20%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	

TO: AIG

Vehicle No : SMV 1197 P

Make & Model : HONDA CIVIC

DATE: 20/4/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	BOOTLID	1	\$ 581.20	\$ <i>bt</i> 581.20
2	BOOTLID BADGE	1	\$ 120.00	\$ <i>nc</i> 120.00
3	BOOTLID EMBLEM(CIVIC)	1	\$ 51.90	\$ <i>nc</i> 51.90
4	BOOTLID EMBLEM(I-VTEC)	1	\$ 76.00	\$ <i>nc</i> 76.00
5	BOOTLID OUTER GARNISH	1	\$ 310.60	\$ <i>cn</i> 310.60
6	BOOTLID LAMP	2	\$ 266.50	\$ <i>x</i> 533.00
7	BOOTLID STOPPER	2	\$ 40.00	\$ <i>x</i> 80.00
8	BOOTLID INNER TRIM	1	\$ 377.40	\$ <i>x</i> 377.40
9	BOOTLID INNER LOCK	1	\$ 298.50	\$ <i>bt</i> 298.50
10	BOOTLID LOCK CATCH	1	\$ 46.00	\$ <i>x</i> 46.00
11	BOOTLID WEATHERSTRIP	1	\$ 210.00	\$ <i>cul</i> 210.00
12	BOOTLID LOCK DETECTOR	1	\$ 217.00	\$ <i>an</i> 217.00
13	TAIL LAMP	2	\$ 388.90	\$ <i>era</i> 777.80
14	TAIL LAMP BOTTOM RETAINER	2	\$ 89.00	\$ <i>cn</i> 178.00
15	REAR BUMPER	1	\$ 765.00	\$ <i>de</i> 765.00
16	REAR BUMPER SIDE RETAINER	2	\$ 128.40	\$ <i>cn</i> 256.80
17	REAR BUMPER REINFORCEMENT	1	\$ 260.00	\$ <i>bb</i> 260.00
18	REAR BUMPER REFLEXTOR	2	\$ 68.90	\$ <i>cn</i> 137.80
19	REAR BUMPER REFLEXTOR GARNISH	2	\$ 157.70	\$ <i>de</i> 315.40
20	REAR BUMPER DIFFUSER	1	\$ 210.00	\$ <i>de</i> 210.00
22	REAR BUMPER TOW COVER	1	\$ 45.00	\$ <i>x</i> 45.00
23	REVERSE SENSOR	<i>2</i> 4	\$ 325.00	\$ <i>nr</i> 1,300.00
24	REVERSE SENSOR WIRING	1	\$ 574.30	\$ <i>x</i> 574.30
25	REAR ALARM BUZZER	1	\$ 178.90	\$ <i>cn</i> 178.90
26	END PANEL	1	\$ 365.00	\$ <i>bt</i> 365.00
27	END PANEL TOP TRIM	1	\$ 125.00	\$ <i>de</i> 125.00
28	REAR FLOOR PANEL	1	\$ 654.30	\$ <i>de</i> 654.30

29	REAR FLOOR PANEL TOP BOARD	1	\$	417.00	\$ <i>de</i> 417.00
30	REAR FENDER INNER TRIM	2	\$	398.70	\$ <i>x</i> 797.40
31	REAR FENDER INNER SHIELD	<i>LH in</i> 2	\$	198.00	\$ <i>R4</i> x 396.00
32	REAR AIR VENT	2	\$	100.00	\$ <i>x</i> 200.00
33	REAR EXHAUST SILENSER	1	\$	887.50	\$ <i>x</i> 887.50
34	REAR EXHAUST MOULTING	2	\$	38.00	\$ <i>x</i> 76.00
35	REAR EXHAUST INSULATOR	1	\$	114.50	\$ <i>x</i> 114.50

Subtotal : \$ 11,933.30

Less 20% \$ 2,386.66

Parts Total : \$ 9,546.64

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR BUMPER CLIP	1	\$ 50.00	\$ <i>30 only</i> 50.00
2	BOOT LID INNER TRIM CLIP	1	\$ 40.00	\$ <i>x</i> 40.00
3	REAR CAR PLATE WITH COVER	1	\$ 80.00	\$ <i>x</i> 80.00
4	TAIL LAMP CLIP	1	\$ 30.00	\$ <i>20 only</i> 30.00
5	TAIL LAMP PANEL INNER SEAL	1	\$ 80.00	\$ <i>x</i> 80.00
6	REAR FENDER INNER TRIM CLIPS	1	\$ 60.00	\$ <i>x</i> 60.00
7	REAR END PANEL TOP GARNISH CLIPS	1	\$ 30.00	\$ <i>20 only</i> 30.00
8	REAR END PANEL INSULATION SEAL	1	\$ 120.00	\$ <i>40</i> 120.00
9	REAR FLOOR PANEL INSULATION SEAL	1	\$ 120.00	\$ <i>x</i> 120.00

SPECIAL NETT \$ 610.00

LABOUR (REAR)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	<i>700</i> \$ 1,600.00
TO SPRAY PAINT AFFECTED AREA	<i>700</i> \$ 1,600.00
TUFF COAT	\$ <i>30</i> 200.00
WIRING CHECK	\$ <i>30</i> 100.00
REMOVE AND REFIX CUSHION SEAT TO FACILITATE REPAIR	\$ <i>60</i> 350.00
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ <i>30</i> 150.00
REMOVE AND INSTALL REAR EXHAUST	\$ <i>x</i> 350.00
REAR CHASSIS ALIGNMENT	\$ <i>x</i> 100.00
TRANSFER BOOTLID MECHANISM	\$ <i>60</i> 150.00
CONDUCT WATER LEAKAGE TEST	\$ <i>x</i> 100.00

Tanfikh 9741549 - WP 21/4/21 @ 1150 pm

L/S Resumy after repair

LABOUR TOTAL \$ 4,700.00

<i>06 days</i>	Total Parts Cost	\$ 10,156.64
<i>Tanfikh @ 11 hours</i>	Total Labour Cost	\$ 4,700.00
	Total Repair Cost	\$ 14,856.64

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: