

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -20%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	

TO: AIG

Vehicle No : SMV 1197 P

Make & Model : HONDA CIVIC

DATE: 20/4/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE	
1	BOOTLID	1	\$ 581.20	\$ bt 581.20	
2	BOOTLID BADGE	1	\$ 120.00	\$ na 120.00	
3	BOOTLID EMBLEM(CIVIC)	1	\$ 51.90	\$ na 51.90	
4	BOOTLID EMBLEM(I-VTEC)	1	\$ 76.00	\$ na 76.00	
5	BOOTLID OUTER GARNISH	1	\$ 310.60	\$ ca 310.60	XNN
6	BOOTLID LAMP	2	\$ 266.50	\$ xnn 533.00	
7	BOOTLID STOPPER	2	\$ 40.00	\$ xnn 80.00	
8	BOOTLID INNER TRIM	1	\$ 377.40	\$ xnn 377.40	
9	BOOTLID INNER LOCK	1	\$ 298.50	\$ bt 298.50	xnn
10	BOOTLID LOCK CATCH	1	\$ 46.00	\$ xnn 46.00	
11	BOOTLID WEATHERSTRIP	1	\$ 210.00	\$ ad 210.00	xnn
12	BOOTLID LOCK DETECTOR	1	\$ 217.00	\$ ad 217.00	xnn
13	TAIL LAMP	2	\$ 388.90	\$ eri 777.80	\$14.80
14	TAIL LAMP BOTTOM RETAINER	2	\$ 89.00	\$ lun 178.00	xnn
15	REAR BUMPER	1	\$ 765.00	\$ de 765.00	
16	REAR BUMPER SIDE RETAINER	2	\$ 128.40	\$ one 256.80	\$192.80
17	REAR BUMPER REINFORCEMENT	1	\$ 260.00	\$ bb 260.00	
18	REAR BUMPER REFLECTOR	2	\$ 68.90	\$ cur 137.80	
19	REAR BUMPER REFLECTOR GARNISH	2	\$ 157.70	\$ de 315.40	
20	REAR BUMPER DIFFUSER	1	\$ 210.00	\$ de 210.00	
22	REAR BUMPER TOW COVER	1	\$ 45.00	\$ xnn 45.00	
23	REVERSE SENSOR	1	\$ 325.00	\$ nr 325.00	\$200
24	REVERSE SENSOR WIRING	1	\$ 574.30	\$ xnn 574.30	xnn
25	REAR ALARM BUZZER	1	\$ 178.90	\$ cur 178.90	xnn
26	END PANEL	1	\$ 365.00	\$ bt 365.00	XR
27	END PANEL TOP TRIM	1	\$ 125.00	\$ de 125.00	xnn
28	REAR FLOOR PANEL	1	\$ 654.30	\$ ko 654.30	xnn

01 -> Angie Yang - 9818
90016128

29	REAR FLOOR PANEL TOP BOARD	225.40	1	\$	417.00	\$ do 417.00	xnn
30	REAR FENDER INNER TRIM		2	\$	398.70	\$ nm X 14797.40	
31	REAR FENDER INNER SHIELD	xnn 411m	2	\$	(198.00)	\$ R4 X 396.00	xnn
32	REAR AIR VENT		2	\$	100.00	\$ nm X 200.00	
33	REAR EXHAUST SILENSER		1	\$	887.50	\$ nm X 887.50	
34	REAR EXHAUST MOULTING	\$	2	\$	38.00	\$ nm X 76.00	
35	REAR EXHAUST INSULATOR		1	\$	114.50	\$ nm X 114.50	

2688.70

2150.96

Subtotal : \$ 11,933.30

Less 20% \$ 2,386.66

Parts Total : \$ 9,546.64

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR BUMPER CLIP	1	\$ 50.00	\$ 30.00 50.00
2	BOOT LID INNER TRIM CLIP	1	\$ 40.00	\$ x nn 40.00
3	REAR CAR PLATE WITH COVER	1	\$ 80.00	\$ x nn 80.00
4	TAIL LAMP CLIP	1	\$ 30.00	\$ 20.00 30.00
5	TAIL LAMP PANEL INNER SEAL	1	\$ 80.00	\$ x nn 80.00
6	REAR FENDER INNER TRIM CLIPS	1	\$ 60.00	\$ x nn 60.00
7	REAR END PANEL TOP GARNISH CLIPS	1	\$ 30.00	\$ 20.00 30.00
8	REAR END PANEL INSULATION SEAL	1	\$ 120.00	\$ 40 120.00
9	REAR FLOOR PANEL INSULATION SEAL	1	\$ 120.00	\$ x nn 120.00

SPECIAL NETT \$ ~~110~~ 610.00 30

LABOUR (REAR)

PRICE

PANEL BEATING, REMOVAL AND REPLACING PARTS	500 700	\$ 1,600.00	400 700
TO SPRAY PAINT AFFECTED AREA	600 700	\$ 1,600.00	400 700
TUFF COAT		\$ 30 200.00	
WIRING CHECK		\$ 80 100.00	
REMOVE AND REFIX CUSHION SEAT TO FACILITATE REPAIR		\$ 60 350.00	
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING		\$ 30 150.00	
REMOVE AND INSTALL REAR EXHAUST		\$ x nn 350.00	
REAR CHASSIS ALIGNMENT		\$ x nn 100.00	
TRANSFER BOOTLID MECHANISM		\$ 60 150.00	xnn
CONDUCT WATER LEAKAGE TEST		\$ x nn 100.00	

Tanfikh 97415441 WP 21/4/21 @ 1150 pm

L/S Resurvey after repair

LABOUR TOTAL \$ 4,700.00 1250

06 days	4101.44	Total Parts Cost	\$ 10,156.64
Tanfikh @ 11 hours	110	Total Labour Cost	\$ 4,700.00
	1610	Total Repair Cost	\$ 14,856.64

5821.44

1584650 #06 days

2150.96

30

950

3130.96, l/s\$2500, 4 days

2150.96

30

1250

3430.96

4152700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To disclose damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: