



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6585P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER COVER	DEFORMED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	CRACKED	451.25	451.25
2	REAR BUMPER BRACKET LH/RH @\$55.80	NOT NECESSARY	111.60	-
1	REAR BUMPER REINFORCEMENT	CRACKED	394.80	394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH	NOT NECESSARY	138.10	-
1	REAR BUMPER LOWER CTR MOULDING	NOT NECESSARY	155.00	-
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	REAR BUMPER TOWING COVER	MISSING	98.80	98.80
1	REAR BUMPER REAR HOOK	NOT NECESSARY	94.60	-
2	REAR BUMPER REFLECTOR LAMP LH/RH @\$41.45	NOT NECESSARY	82.90	-
1	REAR BUMPER UNDER CENTRE COVER	NOT NECESSARY	225.00	-
1	LICENCE LAMP	NOT NECESSARY	85.30	-
1	ANTENNA ASSY-SMARTK	NOT NECESSARY	40.50	-
1	BOOTLID	BENT	2,480.40	2,480.40
2	BOOTLID HINGE LH/RH @\$31.30	TO REPAIR SEE LABOUR	62.60	-
1	BOOTLID LOCK UPPER	NOT NECESSARY	224.00	-
1	BOOTLID LOCK LOWER	NOT NECESSARY	51.30	-
1	KEY LOCK	NOT NECESSARY	141.00	-
1	BOOTLID HYUNDAI PLATE	NECESSARY	24.30	24.30
1	EMBLEM HYBRID	NECESSARY	24.30	24.30
1	EMBLEM-IONIQ	NECESSARY	31.30	31.30
2	BOOTLID ABSORBER LH/RH	NOT NECESSARY	86.70	-
1	BOOTLID LAMP LH	NOT NECESSARY	622.20	-
1	TAILLAMP LH	NOT NECESSARY	697.80	-
	LESS 20% DISCOUNT		-1,401.33	-797.31
			5,605.32	3,189.24

Report Ref No. NS/INC21004971/T1qcn2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>NETT ITEMS</u></b>			
1	BOOTLID COMFORT LOGO STICKER (N)	NECESSARY	30.00	30.00
1	REAR NUMBER PLATE (N)	CRACKED	25.00	25.00
1	BOOTLID COMFORT APP STICKER (N)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (N)	NOT NECESSARY	180.00	-
1	LOGO AND TEL STICKER (N)	NECESSARY	35.00	35.00
	LESS 10% DISCOUNT		-	-12.00
			300.00	108.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BOOTLID HINGE LH/RH.		800.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	WIRING CHARGE.		50.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			1,530.00	1,085.00
	<b>GRAND TOTAL</b>		<b>7,435.32</b>	<b>4,382.24</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>4,382.24</b>

Report Ref No. NS/INC21004971/T1qcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.