



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3359K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT FENDER LH	BENT	945.30	945.30
1	FRT FENDER SHIELD LH	DEFORMED	198.50	198.50
1	FRT FENDER (HYBRID) LH	NECESSARY	86.50	86.50
1	FRT WHEEL CAP LH	CUT	177.70	177.70
1	FRT DOOR LH	BENT	1,264.00	1,264.00
1	WING MIRROR LH	TO REPAIR SEE LABOUR	1,390.10	-
1	WING MIRROR OUTER COVER LH	TO REPAIR SEE LABOUR	141.90	-
1	REAR DOOR LH	BENT	1,258.30	1,258.30
1	ROCKER PANEL GARNISH LH	DEFORMED	576.00	576.00
	LESS 25% DISCOUNT		-1,509.58	-1,126.58
			4,528.72	3,379.72
NETT ITEMS				
1	FRT DOOR COMFORTDELGRO LH (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS LH (N)	NECESSARY	80.00	80.00
1	REAR FENDER (PETROL ONLY) LH (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-18.50	-18.50
			166.50	166.50
LABOUR				
	PANEL BEATING-REAR FENDER LH.INCLUSIVE OF THE REPAIR OF WING MIRROR LH AND WING MIRROR OUTER COVER LH.		800.00	700.00
	SPRAY PAINTING CHARGE.		1,800.00	1,250.00
	CHECK WIRING ETC.		40.00	30.00
	TUFF KOTE.		160.00	40.00
	TRANSFER OF 2 DOORS.		240.00	120.00
			3,040.00	2,140.00
GRAND TOTAL			7,735.22	5,686.22

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			4,550.00
---	--	--	-----------------

Report Ref No. NS/INC21004977/T1vcn2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.