

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC8708D

DOA: 16.04.2021

Date: 19/04/2021

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
1	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER BRACKET RH			\$35.60
1	BOOTLID			\$2,174.90
1	BOOTLID LAMP RH			\$622.20
1	TAIL LAMP RH			\$697.80
1	REAR FENDER RH			\$2,171.40
	<i>Supp emblem 140 - 67.40</i>			
	<i>u H - 63.10</i>			
	<i>u CRD - 52.40</i>			
	SUB TOTAL		2631.40	\$6,829.90
	LESS 20%		2105.12	\$1,365.98
	DISCOUNTED TOTAL			\$5,463.92
	<i>Logo sticker - 30</i>			
	<i>Tel sticker - 30</i>			
	Labour Charge			
	WIRING CHARGE			\$60.00
	TUFF KOTE			\$60.00
	PANEL BEATING			\$800.00
	SPRAY PAINTING CHARGE			\$750.00
	REMOVE/REFIX REVERSE SENSOR			\$60.00
	TOTAL LABOUR		980	\$1,730.00
	ESTIMATE TOTAL		3139.12	\$7,193.92
			4582500	
			3days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97455749 2-3 days
up 19/4/21 @ 420
L/S Resurvey after repair
Tanpin e/whanbun