

Our Job Ref No : 305464365

Date : 22.04.21

**COMFORTDELGRO**

**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. : SHC8708D CTPL

16.04.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **NTUC** --- **FBG2962A**

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

**Final Lumpsum Repair cost**

**\$2,500.00**

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : MS. LOKE YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : Taufikh

Date : 5/5/21

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

VEHICLE I SHC8708D  
NTUC  
305464365

TYPE OF C: TP  
SURVEY B: LKK/ TAUFIKH  
DATE : 22/04/2021

## SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
BOOTLID I40 EMBLEM	1	nec ✓	\$67.90	RESPRAY BOOTLID
BOOTLID 'H' EMBLEM	1	nec ✓	\$63.10	RESPRAY BOOTLID
BOOTLID CRDI EMBLEM	1	nec	\$52.40	RESPRAY BOOTLID
BOOTLID CTPL LOGO STICKER	1	nec ✓	\$30.00	NETT
BOOTLID CTPL TEL NO STICKER	1	nec	\$30.00	NETT
			\$243.40	