

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

EQ Insurance Co. Ltd
 22 Geminill Lane
 Singapore 069257
 Tel : 6223 - 9433
 Fax : 6224 - 3903

Xiao Chen.

Quotation
 DATE : 10.06.2021
 VEH NO : GBK5035K
 MODEL : Toyota Hiace
 D O A : 17.04.2021
 YR REF : GBB6542D

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBK5035K (TOYOTA HIACE)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>dehd</i>	1	496.40 ✓
2	Rear Bumper Side Retainer - LH & RH <i>new</i>	2	110.40 x
3	Rear Bumper Lower Bracket <i>2 pieces Bent</i>	4	116.00 58.
4	Rear End Panel <i>Dented</i>	1	581.10 ✓
5	Rear End Panel Inner <i>Repair</i>	1	936.20 x
6	Tail Lamp - LH <i>crack</i>	1	365.10 ✓
7	Tail lamp Lower Apron - LH <i>new</i>	1	101.20 x
8	Tail lamp Panel - LH <i>Dented</i>	1	318.40 ✓
9	Tailgate <i>Dented</i>	1	1,755.90 ✓
10	Tailgate Lock <i>new</i>	1	287.10 ✓
11	Tailgate Weatherstripe <i>new</i>	1	387.90 x
12	Tailgate Outer Garnish <i>new</i>	1	364.70 x
13	Toyota Logo <i>new</i>	1	70.50 ✓
14	Toyota Hiace Sticker <i>new</i>	1	57.60 ✓

3990.10.

2992.57

\$ 5,948.50
 Less 25% (1,487.13)
 \$ 4,461.38

S/NET ITEMS

1	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Reverse Sensor <i>new</i>	1	280.00 x
4	Rear End Panel Sealant <i>new</i>	1	60.00 ✓
5	Tailgate Glass Sealant <i>new</i>	1	60.00 ✓
6	70km/h Sticker <i>new</i>	1	10.00 ✓

160

\$ 440.00

Total Parts

\$ 4,901.38

RE: ESTIMATE FOR ACCIDENT REPAIR GBK5035K (TOYOTA HIACE)

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00	900
2	To putty & spray up paint works	\$	1,200.00	900
3	To check wiring	\$	50.00	30
4	To remove reverse sensor	\$	100.00	50
5	To spray tuff coat	\$	150.00	80
6	To remove tailgate glass	\$	180.00	120
7	To transfer tailgate fittings	\$	150.00	80
Total Labour		\$	3,030.00	
Grand Total		\$	7,931.38	

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 5312.57
CP/P)
06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: