



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21004985/Kvf3e2	
			Date: 04/05/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMS 7404T	Veh. Inspected	SMH 1689K
	Policy No.	D21MTPV01002996	Coverage (\$)	0.00
	Claim No.	CMTD2101226/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	21/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	GP71213382	Colour	METALLIC GREY
	Odometer	273169 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	MAXXIS	7 mm
	L/H Front Tyre	195/55 R15	MAXXIS	7 mm
	R/H Rear Tyre	195/55 R15	MAXXIS	7 mm
	L/H Rear Tyre	195/55 R15	MAXXIS	7 mm
4. Description of Damages				
	REAR NO DAMAGE.			
5. General Information				
	Accident Date	19/04/2021	Inspection Date	21/04/2021
	Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			