

ASS. BY:

REF:

CS | MSG 21004986 | Dvj3

ASSIGNMENT

From: _____ Date: _____

Estimate Cost: _____

OD / TP RES / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Work m/s _____

of _____

Insured _____

Policy # _____

Claim # _____

Sum Insured: _____

Excess: _____

(Check Record)

Make of: _____

(Police Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoTurn Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBG 8218 B Yr Regn: Nov / 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan Cabstar C.C. 2953Colour: Silver A/C: Insured / Std / Nil / NASp. Reading: 91021 T/Radio: Insured / Std / Nil / NAEng/No: ZD30026561NC/No: JH13C2F24Z0860356

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

195 R15C

R: _____

165 R13C (double)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dunlop

Front

Rear

R/Bal

S

mm

R/Bal

S/S

mm

L/Bal

S

mm

L/Bal

S/S

mm

D.O.A.

19/04/221

D.O.L

22/04/221


Survey held at

JWG AMK

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
	MSG GBK 5428K
	MV 52K
	LTA 30.7K
	NL 21.3K

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Report Format:

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: MSIG INSURANCE SINGAPORE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING GBK5428K [YOUR INSURED] & GBG8218B [OUR CLIENT]
ON 19/04/2021.

ESTIMATED REPAIR COSTS FOR GBG8218B

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	FRONT WIPER MOTOR <i>HH</i>	\$ 590.00	X
2PCS	FRONT WIPER ARM LH / RH @ \$329.00 EACH <i>HH</i>	\$ 658.00	X
1PC	FRONT WIPER LINK <i>HH</i>	\$ 289.00	X
1PC	FRONT WIPER GARNISH <i>SVL</i>	\$ 728.00	X
1PC	FRONT WINDSCREEN MOULDING <i>Hec</i> 158.50	\$ 399.00	X ✓
1PC	FRONT PANEL <i>Dent</i> 1412.70	\$ 1,490.00	✓
1PC	FRONT PANEL 'CABSTAR' EMBLEM <i>Hec</i> 55.10	\$ 79.00	✓
1PC	FRONT PANEL INNER <i>new</i>	\$ 1,992.00	X
1PC	FRONT GRILLE <i>broken</i> 461.90	\$ 582.00	✓
1PC	FRONT GRILLE LOGO <i>Hec</i> 58.50	\$ 72.00	✓
1PC	FRONT GRILLE BASE <i>2 HH</i>	\$ 622.00	X X
1PC	FRONT BUMPER <i>cracked</i> 698.20	\$ 701.00	✓
1PC	FRONT BUMPER BEAM <i>2 Bt / Dent</i> 481.00	\$ 882.00	X ✓
2PCS	HEAD LAMP LH / RH @ \$1,490.00 EACH <i>broken / crack</i> 518.50 x 2	\$ 2,980.00	1037.00
2PCS	SIDE MIRROR RECTANGLE LH / RH @ \$671.00 EACH <i>HH</i>	\$ 1,342.00	X
2PCS	SIDE MIRROR ROUND LH / RH @ \$379.00 EACH <i>HH</i>	\$ 758.00	X
2PCS	SIDE MIRROR STAY LH / RH @ \$401.00 EACH <i>HH</i>	\$ 802.00	X 389.90
2PCS	FRONT SIDE PANEL LH / RH @ \$610.00 EACH <i>o/s HH w/s Dent</i>	\$ 1,220.00	✓
1PC	A/C CONDENSOR <i>HH</i> 1,892.00	\$ 1,892.00	X
1PC	A/C CONDENSOR DISCHARGE HOSE <i>2 Bt</i> 398.40	\$ 782.00	2 ✓
1PC	A/C CONDENSOR SUCTION HOSE <i>2 Bt</i> 436.70	\$ 1,092.00	2 ✓
1PC	A/C BLOWER <i>2 broken</i> 1666.20	\$ 1,720.00	2 ✓
1PC	A/C COOLING COIL <i>2 money broken</i> 1433.10	\$ 1,882.00	2 ✓
1PC	DASHBOARD ASSY <i>HH</i>	\$ 2,680.00	X
2PCS	FRONT DOOR LH / RH @ \$1,890.00 EACH <i>new</i>	\$ 3,780.00	X
1PC	TAILGATE <i>Dent</i> 1399.00	\$ 2,491.00	✓
3PCS	TAILGATE HINGE @ \$80.00 EACH <i>1 pc Dent 2 pc HH</i>	\$ 240.00	✓
1PC	TAILGATE NISSAN STICKER <i>Hec</i>	\$ 100.00	✓
1PC	TAILGATE LOCK LH / RH @ \$240.00 EACH <i>SVL</i>	\$ 480.00	X
2PCS	SIDEGATE LH / RH @ \$2,980.00 EACH <i>HH</i>	\$ 5,780.00	X

1PC	SIDEGATE LOCK LH / RH @ \$301.00 EACH HH	\$ 602.00	X
1PC	SIDEGATE LOCK BRACKET LH / RH @ \$175.00 EACH HH	\$ 350.00	X
1PC	REAR END PANEL <i>Dent</i>	545.10 \$ 2,450.00	✓
1PC	REAR FLOOR PANEL EXTENSION HH	\$ 2,140.00	X
1PC	REAR STOPPERS LH / RH @ \$79.00 EACH SVL	\$ 158.00	X
1PC	REAR STOPPERS BRACKET LH / RH @ \$198.00 EACH HH	\$ 396.00	X
1PC	TAIL LAMP LH / RH @ \$672.00 EACH <i>broken</i> 297.50 x 2 = 595.00	\$ 1,344.00	✓
1PC	REAR NO. PLATE LAMP HH	\$ 129.00	X
1PC	REAR CHASSIS EXTENSION LH / RH @ \$4,100.00 EACH <i>key</i>	\$ 8,200.00	X
10PCS	REAR CHASSIS BRACKET @ \$340.00 EACH HH	\$ 3,400.00	X
1PC	SPARE TYRE BRACKET HH	\$ 398.00	X
1PC	SPARE TYRE BOLT HH	\$ 219.00	X
1PC	SPARE TYRE CARRIER HH	\$ 332.00	X
2PC	FRONT DOOR LH / RH @ \$1200 EACH <i>respect</i>	\$ 2400.00	X
1PC	FRONT PILLER LH \$1800 <i>key</i>	\$ 1800.00	X
1PC	FLOOR PANEL <i>key</i>	\$ 2000.00	X

4PC WINDSCREEN Moulding \$850.00 X

repeated

PARTS SUM: \$ 59,223.00

PARTS LESS 10%: \$ 5,922.30

PARTS TOTAL: \$ 53,300.70

1130.63

10175.67

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY FRONT & REAR NO. PLATE <i>front nt rear HH</i>	\$ 200.00	351-
*	TO SUPPLY TAILGATE CHECKERED PLATE <i>HH</i>	600- \$ 2,000.00	✓ 4001-
*	TO SUPPLY SIDEGATE CHECKERED PLATE HH	\$ 4,000.00	X
*	TO SUPPLY SIDEGATE RAILING L + R HH	\$ 3,200.00	X
*	TO SUPPLY 70KM STICKER <i>HH</i>	\$ 50.00	201-
*	TO SUPPLY 6PAX STICKER <i>HH</i>	\$ 50.00	201-
*	TO SUPPLY 1 SET REVERSE SENSOR <i>broken</i>	\$ 300.00	2001-
*	TO SUPPLY FRONT WINDSCREEN SEALANT <i>HH</i>	\$ 80.00	401-
*	TO SUPPLY FRONT WINDSCREEN DAMPING SEAL HH	\$ 30.00	X
*	TO SUPPLY FRONT WIPER GARNISH CLIPS HH	\$ 50.00	X
*	TO SUPPLY FRONT PANEL CLIPS HH	\$ 50.00	X
*	TO SUPPLY FRONT PANEL INNER SEALANT HH <i>730.00</i>	\$ 80.00	X
*	TO SUPPLY FRONT GRILLE CLIPS <i>HH</i>	\$ 50.00	151-
*	TO SUPPLY HEAD LAMP CLIPS HH	\$ 50.00	X
*	TO SUPPLY SIDE MIRROR GARNISH CLIPS HH	\$ 50.00	X
*	TO SUPPLY SIDE PANEL CLIPS HH	\$ 50.00	X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 4,000.00	20001- 18001-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 4,000.00	10001-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	401-
*	TO RNR A/C CONDENSOR TO FACILITATE REPAIRS	\$ 200.00	1201-
*	TO RNR FRONT WINDSCREEN TO FACILITATE REPAIRS	\$ 400.00	1001-

*	TO RNR A/C BLOWER TO FACILITATE REPAIRS	\$ 200.00	80/-
*	TO RNR A/C COOLING COIL TO FACILITATE REPAIRS	\$ 200.00	44
*	TO RNR DASHBOARD ASSY TO FACILITATE REPAIRS	\$ 600.00	150/-
*	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	\$ 200.00	44
*	TO RNR & REALIGN REAR DECK TO FACILITATE REPAIRS	3570 w	\$ 1,000.00 250/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	30/-

LABOUR & S/N TOTAL: \$ 21,590.00


GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 74,890.70

22/04/2021 @ 0915hr
Hot Air
2/5mm 10 days

14,475.67
Supp 1026.50
15502.17
L/S 12,400/-

P. njan

LKK Auto Check part prices.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: MSIG INSURANCE SINGAPORE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING GBK5428K [YOUR INSURED] & GBG8218B [OUR CLIENT]

ON 19/04/2021.

SUPPLYMENTARY ITEMS FOR GBG8218B

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>
1PC	RADIATOR ASSY <i>1st Dam</i>	<i>980.00</i> \$ 1,821.51
1PC	RADIATOR FAN BLADE <i>broken</i>	<i>105.00</i> \$ 294.30
		PARTS SUM: \$ 2,116.01
		PARTS LESS 10%: \$ 211.60
		PARTS TOTAL: \$ <u>1,904.41</u>

1085.00
976.50

LABOUR & SPECIAL NETT ITEMS

* TO RNR RADIATOR ASSY TO FACILITATE REPAIRS \$ 150.00

LABOUR & SPECIAL NETT TOTAL: \$ 150.00

GRAND TOTAL SUPPLEMENTARY REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 2,054.41

[Signature]
2kk Auto

1026.50