

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERS SINGAPORE 048623			Ref: CS/SMO21004988/Kvf3 Date: 21/04/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKF 7937P	Veh. Inspected	SH 2359K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2101250/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	21/04/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/04/2021	Inspection Date	21/04/2021	
Survey held at	CHOON HOCK MOTOR TRADING CO BLK 176 SIN MING DRIVE #05-03 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				