



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD  
(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Ref: CS3/AWA20008399/Evf3e2-1

Date: 29/04/2021

Code: AWA

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLH 2739E	<b>Veh. Inspected</b>	SJN 8718T
<b>Policy No.</b>	BVPISB0047511903	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	NSV2000226/HLF	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HEW LEE FONG	<b>Assign Date</b>	21/04/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA VIOS	<b>c.c</b>	1497
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	MR053HY9305096389	<b>Colour</b>	GOLD
<b>Odometer</b>	123482 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	185/60 R15	YOKOHAMA	4 mm
<b>L/H Front Tyre</b>	185/60 R15	YOKOHAMA	4 mm
<b>R/H Rear Tyre</b>	185/60 R15	YOKOHAMA	4 mm
<b>L/H Rear Tyre</b>	185/60 R15	YOKOHAMA	4 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	13/08/2020	<b>Inspection Date</b>	14/08/2020
<b>Survey held at</b>	SIN HOCK LEE MOTOR REPAIR 51 UBI AVENUE 1 #01-09 PAYA UBI INDUSTRIAL PARK . SINGAPORE 408933		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**