

Estimates on Miscellaneous Items  
There are no new miscellaneous items selected.

### Estimates on Labour

No	Particulars	Lab.Type	Amount	
<b>Labour Items</b>				
1	TOWING	New	60.00	✓
2	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, REAR BOTH ATTACHMENT, LOCK ASSY, CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR BOTH FENDERS & REALIGN THE SAME	New	800.00	700
3	PUTTY & RESPRAY ON REAR BOTH FENDERS, REAR BOOT, REAR PANEL, REAR BUMPER & REAR AFFECTED AREAS	New	800.00	720
4	REMOVE & REFIX AIRCON, CHECK, VACUUM & REFILL GAS	New	100.00	✓
5	REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, GRILLE, BONNET & ATTACHMENT, RADIATOR & MOTOR, FRT FENDERS, CUT, WELD & RENEW FRT SUPPORT PANEL, KNOCK & REPAIR FRT FENDERS & REALIGN THE SAME	New	700.00	600
6	PUTTY & RESPRAY ON FRT BUMPER, REINFORCEMENT, SUPPORT PANEL, BONNET, FRT FENDERS & FRT AFFECTED AREAS	New	700.00	600
7	REMOVE & REFIX REVERSE SENSOR, REVERSE CAMERA & RESET SYSTEM	New	50.00	✓
8	RUSTPROOFING	New	60.00	✓
Gross Labour Cost (S\$)			3,270.00	

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >