



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2106641

INV Date 24/09/2021

Reference CS/EQI21004998/Gtf3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SBS 6184P
Insured Veh. YN 1491P
Claim No. DM21HO00565-JG
Policy No. DMCPHQ20-004039
Accident Date 09/04/2021
Inspection Date 21/04/2021

Description	Total
Survey Inspection	160.00
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Ref: CS/EQI21004998/Gtf3e2

Date: 24/09/2021

Code: EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 1491P	Veh. Inspected	SBS 6184P
Policy No.	DMCPHQ20-004039	Coverage (\$)	0.00
Claim No.	DM21HO00565-JG	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	21/04/2021

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CITARO O530	c.c	6374
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WEB62808323123148	Colour	PURPLE / RED
Odometer	686903 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	6/6 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/04/2021	Inspection Date	21/04/2021
Survey held at	Hougang Depot 4, Defu Avenue 1 Singapore 539536		
Repairer	SBS TRANSIT LTD (HQ)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 6184P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
4	BUFFER;RADIATOR PANEL	NECESSARY	10.00	10.00
1	PLATE;RADIATOR PANEL	NECESSARY	9.00	9.00
1	SIGNAL LED LIGHT;AMBER	CRACKED	36.00	36.00
1	TAIL LAMP ASSY;RIGHT;RR	CRACKED	433.00	433.00
1	MOUNTING;RADIATOR PANEL	BENT	33.00	33.00
2	LOCK;RADIATOR PANEL	MISSING	36.00	36.00
2	TREENAIL	NECESSARY	2.00	2.00
1	FACE BAR.REAR BUMPER.W/RR FOGLAMP.O/S	CRACKED	364.00	364.00
4	GROMMET;TAIL LAMP BRACKET;ELECTRICAL	NECESSARY	15.00	15.00
1	GLASS.PANEL.SINGLE GLAZING.NO 7.O/S	CRACKED	389.00	389.00
1	BRACKET RH;RR BUMPER	BENT	16.00	16.00
1	RADIATOR PANEL;O/S;RR	MISSING	2,385.00	2,385.00
1	MOUNTING;RADIATOR PANEL	NECESSARY	33.00	33.00
1	HANDLE;RADIATOR PANEL	MISSING	11.00	11.00
1	INTERCOOLER ASSY.MB CITARO XR ^	CUT	2,650.00	2,650.00
1	PILLAR O/S;RR PANEL	CRACKED	588.00	588.00
2	SCREW;SPECIAL SHAPE;RR BUMPER	NECESSARY	1.00	1.00
1	BUSHING;RADIATOR PANEL	NECESSARY	1.00	1.00
4	SCREW;RADIATOR PANEL	NECESSARY	4.00	4.00
1	PLATE;RADIATOR PANEL	NECESSARY	9.00	9.00
2	BOLT.BUMPER.REAR	NECESSARY	2.00	2.00
1	BALL STUD.OUTSIDE FLAPS.RH	NECESSARY	2.00	2.00
1	BUSHING;RADIATOR PANEL	NECESSARY	1.00	1.00
1	GAS SPRG;RADIATOR PANEL	NECESSARY	74.00	74.00
			7,104.00	7,104.00
LABOUR				
	(2) WORKSHOP LABOUR.	NOT NECESSARY	192.00	-
	CONTRACTOR'S REPAIR CHARGES.		1,800.00	1,800.00
			1,992.00	1,800.00
GRAND TOTAL			9,096.00	8,904.00

Report Ref No. CS/EQI21004998/Gtf3e2



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			8,904.00
---	--	--	-----------------

Report Ref No. CS/EQI21004998/Gtf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 15/04/2021 10:16 (SGT)
Date of Accident 09/04/2021 17:21 (SGT)
Exact Location of Accident Near 10 Jln Serene, Singapore 258748
Additional Location Information X junction btw Whitley Rd & Bukit Timah Rd
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SBS6184P

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner SBS TRANSIT
Company Reg No 1XXXXXXXXXXTE01
Email Address angkiats@sbstransit.com.sg
Mobile Phone No (Phone) +65-99999999
Alternative Phone No (Office) +65-63837805

VEHICLE PARTICULARS

Manufacturer Mercedes
Model Citaro
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Bus
Transmission Auto
CC 6374

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd
Type of Coverage ActLiability
Fleet Policy No
Policy Number D-20095429MFBP
Cover Note Number -

DRIVER

Name of Driver Neo Teng Joon
NRIC No SXXXX902G

Date Of Birth	16/05/1958
Occupation	Outdoor
Date Of Driving Pass	28/02/2000
Driving experience	21 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-938865294
Alt. Phone Number	-
Email Address	angkiats@sbstransit.com.sg
Address	Blk 529 Bedok North St 3 #05-622
Address complement	-
Postcode	460529
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	11
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Male

PASSENGER 2

Name	UNKNOWN
Gender	Female

PASSENGER 3

Name	UNKNOWN
Gender	Male

PASSENGER 4

Name	UNKNOWN
Gender	Female

PASSENGER 5

Name	UNKNOWN
Gender	Male

PASSENGER 6

Name	UNKNOWN
Gender	Female

PASSENGER 7

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

On the mentioned date and time, I was doing Svc 156 in SBS6184P. I was travelling along Whitley Rd. I stopped at the X junction as the traffic lights turned red. It was heavy traffic at that moment. There is a lorry, YN1491P stopped behind my bus. While waiting for the traffic to turn green, the lorry suddenly overtake my bus. It resulted in my OSR lighting & N Panel damaged. I informed OCC and was told to exchange particulars. I resumed svc shortly. 10 pax onboard. No injury. That's all.

ATTACHMENT(S)

Are accident photos available for attachment? No
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN1491P
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Goods vehicle
 Name of Driver Lim Yong Chua
 Contact Number (Phone) +65-87772641
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage SIDE SWIPE - SAME DIRECTION
 Details of property damaged in accident Left panel damaged and scratched
 No. Of Passenger (Including Driver) -

SKETCH PLAN

W/1649/2021
9/4/21

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

48 13-04-21

Policyholder's Signature / Date & Time	Driver's Signature (If driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel
--	--	---

Sketch Plan





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBS 6184P

INSPECTION








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R










LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

