

Certification for Bus Repairs



CBR REF NO. : HG20212701

Depot : HG Report No.: W16492021 BUS VEHICLE NO. : SBS6184P
 Driver's Co no. & Name : 17321 Neo Teng Joon
 Accident Date : 09/04/2021

Date in : 09/04/2021

Date Out : 25/05/2021

Yr Of Reg	Make / Model	Chassis No.
2012	MB Citaro O530, SD, AC, 2 Axle	WEB62808323123148

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
30600010	BUFFER;RADIATOR PANEL ✓ NEC	4	\$10.00
30600016	PLATE;RADIATOR PANEL ✓ NEC	1	\$9.00
30600021	SIGNAL LED LIGHT;AMBER ✓ CRA	1	\$36.00
30600030	TAIL LAMP ASSY;RIGHT;RR ✓ CRA	1	\$433.00
30600012	MOUNTING;RADIATOR PANEL ✓ BT	1	\$33.00
30600015	LOCK;RADIATOR PANEL ✓ MIS	2	\$36.00
30600105	TREENAIL ✓ NEC	2	\$2.00
30600745	FACE BAR.REAR BUMPER.W/RR FOGLAMP.O/S ✓ CRA	1	\$364.00
30600156	GROMMET;TAIL LAMP BRACKET;ELECTRICAL ✓ NEC	4	\$15.00
30117528	GLASS.PANEL.SINGLE GLAZING.NO 7.O/S ✓ CRA	1	\$389.00
30311602	BRACKET RH;RR BUMPER ✓ BT	1	\$16.00
30600002	RADIATOR PANEL;O/S;RR ✓ MIS	1	\$2,385.00
30600011	MOUNTING;RADIATOR PANEL ✓ NEC	1	\$33.00
30600009	HANDLE;RADIATOR PANEL ✓ MIS	1	\$11.00
12205000	INTERCOOLER ASSY. MB CITARO XR ^ ✓ CUT	1	\$2,650.00
30600230	PILLAR O/S;RR PANEL ✓ CRA	1	\$588.00
30311605	SCREW;SPECIAL SHAPE;RR BUMPER ✓ NEC	2	\$1.00
30600017	BUSHING;RADIATOR PANEL ✓ NEC	1	\$1.00
30600013	SCREW;RADIATOR PANEL ✓ NEC	4	\$4.00
30600016	PLATE;RADIATOR PANEL ✓ NEC	1	\$9.00
30311607	BOLT.BUMPER.REAR ✓ NEC	2	\$2.00
30600755	BALL STUD.OUTSIDE FLAPS.RH ✓ NEC	1	\$2.00
30600017	BUSHING;RADIATOR PANEL ✓ NEC	1	\$1.00
30600014	GAS SPRG;RADIATOR PANEL ✓ NEC	1	\$74.00

TOTAL FOR PARTS		S\$	7104.00
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	SS	192.00
2	Contractor's repair charges	SS	1800.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST		S\$	1992.00
Repair cost of Advertisement / Livery		S\$	-
TOTAL DAMAGE		S\$	9096.00

8904

5 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Certification for Bus Repairs



CBR REF NO. : HG20212701

Depot : HG

Report No.: W16492021

BUS VEHICLE NO. : SBS6184P

Driver's Co no. & Name : 17321 Neo Teng Joon

Accident Date : 09/04/2021

Date in : 09/04/2021

Date Out : 25/05/2021

Yr Of Reg	Make / Model	Chassis No.
2012	MB Citaro O530, SD, AC, 2 Axle	WEB62808323123148
TOTAL DAMAGE		S\$ 9096.00
Overheads		S\$ 2728.80
Towing Charges		S\$ -
Repair Period : 5 day(s)	Loss of Use	S\$ 1781.45
TOTAL LOSS		S\$ 13606.25

Prepared By : Zakaria Bin Ahmad

Date : 26/06/2021

Approved By
Workshop Mgr : Aw Boon Huan

Date : 29/06/2021

	Survey Fee	refer to Group Claims
TOTAL DUE		S\$ 13606.25

Acknowledged By
Depot Safety : Ang Kiat Siang

Date : 29/06/2021

* This is computer generated document and does not require signature