

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find   Next
---	---	---	--------	---	---	---	---	------	---	---	-------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref:	CS/EQI21004998/Gtf3
5 MAXWELL ROAD		Date:	21/04/2021
#17-00 TOWER BLOCK			
MND COMPLEXSINGAPORE 069110		Code:	EQI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	YN 1491P	Veh. Inspected	SBS 6184P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	21/04/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	09/04/2021	Inspection Date	21/04/2021
Survey held at	Hougang Depot 4, Defu Avenue 1 Singapore 539536		
Repairer	SBS TRANSIT LTD (HQ)		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			