

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA 125

Engine/Chassis No.:


Date of accident:

Damaged area: Multiple

Date: 01/07/2021

Claim Type: TP

VRN: FBP9390G



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Head lamp	1	\$ 150.00	\$ 150.00
2	Head lamp cowling	1	\$ 75.00	\$ 75.00
3	Head lamp garnish	1	\$ 95.00	\$ 95.00
4	Front tyre	1	\$ 150.00	\$ 150.00
5	Front wheel rim	1	\$ 280.00	\$ 280.00
6	Front wheel fender	1	\$ 65.00	\$ 65.00
7	Head lamp bracket	1	\$ 25.00	\$ 25.00
8	Front cowling	1	\$ 70.00	\$ 70.00
9	Front cowling logo	1	\$ 18.00	\$ 18.00
10	Speedometer	1	\$ 315.00	\$ 315.00
11	Front brake disc	1	\$ 85.00	\$ 85.00
12	Front brake caliper	1	\$ 265.00	\$ 265.00
13	ERP unit	1	\$ 160.00	\$ 160.00
14	Side fairing - LH	1	\$ 145.00	\$ 145.00
15	Side fairing - RH	1	\$ 145.00	\$ 145.00
16	Side fairing logo	1	\$ 18.00	\$ 18.00
17	Front signal lamp LH	1	\$ 35.00	\$ 35.00
18	Front signal lamp RH	1	\$ 35.00	\$ 35.00
19	Clutch lever	1	\$ 28.00	\$ 28.00
20	Balancer set	1	\$ 50.00	\$ 50.00
21	Handle bar	1	\$ 85.00	\$ 85.00
22	Mirror set	1	\$ 60.00	\$ 60.00
23	Front foot rest	2	\$ 28.00	\$ 56.00
24	Rear foot rest	2	\$ 28.00	\$ 56.00
25	Gear pedal	1	\$ 38.00	\$ 38.00
26	Main stand	1	\$ 45.00	\$ 45.00
27	Swing arm	1	\$ 295.00	\$ 295.00
28	Swing arm shaft	1	\$ 35.00	\$ 35.00
29	Engine side cover	1	\$ 185.00	\$ 185.00
30	Front fork assy LH	1	\$ 140.00	\$ 140.00
31	Front fork assy RH	1	\$ 140.00	\$ 140.00
32	Front fork bracket	1	\$ 80.00	\$ 80.00

Repair Estimate

33	Rear wheel fender	1	\$ 75.00	\$ 75.00
34	Rear exhaust/muffler	1	\$ 320.00	\$ 320.00
Subtotal				\$ 3,819.00
List discount				10.00%
Total				\$ 3,437.10

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Box carrier	1	\$ 120.00	\$ 120.00
2	Top box	1	\$ 200.00	\$ 200.00
3	Rear licence plate	1	\$ 20.00	\$ 20.00
4	Fork oil	1	\$ 20.00	\$ 20.00
5	Fork seal	4	\$ 10.00	\$ 40.00
6	Sticker set	1	\$ 120.00	\$ 120.00
Total				\$ 520.00

Labour			
No.	Description	Work unit	Amount
1	Towing service.		\$ 50.00
2	To realign rear wheel swing arm and chassis.		\$ 100.00
3	To check wiring system.		\$ 30.00
4	To remove and refix rear box and bracket.		\$ 40.00
5	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.		\$ 400.00
6	Supply spray paint material and necessary items to respray affected area / panel.		\$ 300.00
Total labour			\$ 920.00

Estimate Grand Total	\$ 4,877.10
-----------------------------	--------------------