

Repair Estimate

Not Authorized

8698.40

Recurring After Repair

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA 125

Engine/Chassis No.:


Date of accident:

Damaged area: Multiple

Date: 01/07/2021

Claim Type: TP

VRN: FBP9390G



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Head lamp	1	\$ 150.00	\$ 150.00
2	Head lamp cowling	1	\$ 75.00	\$ 75.00
3	Head lamp garnish	1	\$ 95.00	\$ 95.00
4	Front tyre	1	\$ 150.00	\$ 150.00
5	Front wheel rim	1	\$ 280.00	\$ 280.00
6	Front wheel fender	1	\$ 65.00	\$ 65.00
7	Head lamp bracket	1	\$ 25.00	\$ 25.00
8	Front cowling	1	\$ 70.00	\$ 70.00
9	Front cowling logo	1	\$ 18.00	\$ 18.00
10	Speedometer	1	\$ 315.00	\$ 315.00
11	Front brake disc	1	\$ 85.00	\$ 85.00
12	Front brake caliper	1	\$ 265.00	\$ 265.00
13	ERP unit	1	\$ 160.00	\$ 160.00
14	Side fairing - LH	1	\$ 145.00	\$ 145.00
15	Side fairing - RH	1	\$ 145.00	\$ 145.00
16	Side fairing logo	1	\$ 18.00	\$ 18.00
17	Front signal lamp LH	1	\$ 35.00	\$ 35.00
18	Front signal lamp RH	1	\$ 35.00	\$ 35.00
19	Clutch lever	1	\$ 28.00	\$ 28.00
20	Balancer set	1	\$ 50.00	\$ 50.00
21	Handle bar	1	\$ 85.00	\$ 85.00
22	Mirror set	1	\$ 60.00	\$ 60.00
23	Front foot rest	1	\$ 28.00	\$ 56.00
24	Rear foot rest	2	\$ 28.00	\$ 56.00
25	Gear pedal	1	\$ 38.00	\$ 38.00
26	Main stand	1	\$ 45.00	\$ 45.00
27	Swing arm	1	\$ 295.00	\$ 295.00
28	Swing arm shaft	1	\$ 35.00	\$ 35.00
29	Engine side cover	1	\$ 185.00	\$ 185.00
30	Front fork assy LH	1	\$ 140.00	\$ 140.00
31	Front fork assy RH	1	\$ 140.00	\$ 140.00
32	Front fork bracket	1	\$ 80.00	\$ 80.00

X
300.00

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

Repair Estimate

33	Rear wheel fender	1	\$ 75.00	\$ 75.00	X
34	Rear exhaust/muffler	1	\$ 320.00	\$ 320.00	X
Subtotal				\$ 3,819.00	
List discount				10.00%	
Total				\$ 3,437.10	

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Box carrier	1	\$ 120.00	\$ 120.00	✓
2	Top box	1	\$ 200.00	\$ 200.00	X
3	Rear licence plate	1	\$ 20.00	\$ 20.00	125w
4	Fork oil	1	\$ 20.00	\$ 20.00	X
5	Fork seal	4	\$ 10.00	\$ 40.00	X
6	Sticker set	1	\$ 120.00	\$ 120.00	505w
Total				\$ 520.00	

Labour				
No.	Description	Work unit	Amount	
1	Towing service.		\$ 50.00	3ok
2	To realign rear wheel swing arm and chassis.		\$ 100.00	X
3	To check wiring system.		\$ 30.00	101
4	To remove and refix rear box and bracket.		\$ 40.00	X
5	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.		\$ 400.00	1201
6	Supply spray paint material and necessary items to respray affected area / panel.		\$ 300.00	X
Total labour			\$ 920.00	
Estimate Grand Total			\$ 4,877.10	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: