

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: PC 87915
at Workshop m/s Choo m/s
of _____
Insured: GBG 53244
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$10k.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS B 367L
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC 87915 Yr Regn: 23/6/11
Type: M.Car / M.Cycle Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or NA / Hirof 10 seater
Make: Toyota hiace c.c. 2982
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 358779 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JTFST22P20001065
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Good / Jammed / Leaked / Burnt or
Brake: Good / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/80 R15
R: _____

6 / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm	
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm	
D.O.A. <u>19/4/21</u>		D.O.I. <u>21/4/21</u>	

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

LM O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction have GA
B. by Bk. Bonnet spot type

5/8/21 4/3 \$ 8100 confirmed with Alan.

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SPORE 417883

Uth Jasper

not Anthony
Uth
21/4/21
1/5 \$8100
5 days

VEHICLE No: PC 8791S

1PC	FRONT BUMPER	Dis	681.10	\$822.10 ✓
1PC	FRONT BUMPER SIDE HOLDER O/S	CNE		\$105.90 ✓
1PC	FRONT BUMPER REINFORCEMENT	Buf	485.10	\$611.20 ✓
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	Torn	105.00	\$145.00 ✓
1PC	FRONT BUMPER FOG LAMP O/S	NA		\$425.00 X
1PC	FRONT BUMPER CENTRE GRILLE	De/Torn	166.20	\$188.90 ✓
1PC	FRONT GRILLE	CNE	485.10	\$688.10 ✓
1PC	HEADLAMP O/S	CNE	704.35	\$1,455.10 ✓
1PC	FRONT DOOR O/S	Dis	1548.10	\$1,845.20 ✓
2PCS	FRONT DOOR HINGES @\$115.00	lower Buf		\$230.00 1PC
1PC	FRONT DOOR CHECKER O/S	SVC		\$151.00 X
1PC	FRONT DOOR INNER LOCK O/S	SVC		\$435.10 X
1PC	FRONT DOOR INNER RUBBER O/S	rec	182.00	\$311.80 ✓
1PC	FRONT DOOR INNER TRIM BOARD O/S	De/Torn	645.20	\$655.10 ✓
1SET	FRONT DOOR INNER TRIM BOARD CLIPS O/S	rec		\$50.00 ✓
1PC	FRONT DOOR MIRROR ASSY O/S	Damaged	599.10	\$1,050.00 ✓
1PC	FRONT DOOR INNER OUTER PILLAR O/S	Dis/Buf	899.10	\$1,022.80 ✓
1PC	FRONT STEP PANEL O/S	R		\$455.10 X
1PC	FRONT STEP GARNISH O/S	Torn	265.30	\$422.10 ✓
1PC	FRONT WHEEL ARCH PANEL O/S	R		\$545.50 X
1PC	BONNET SPORT	Buf	1200	\$1,450.00 ✓
1PC	BONNET INNER LOCK	SVC		\$165.10 X
1PC	FRONT CORNER PANEL O/S	Dis	322.20	\$455.10 ✓
1PC	AIR CLEANER BOX ASSY	CNE	680.50	\$820.20 ✓
1PC	FRONT WIRE HARNESS ASSY	R		\$655.20 X
1PC	FRONT WIRE HARNESS BRACKET	CNE	189.20	\$205.20 ✓
1PC	FRONT BRAKE BOOSTER PUMP	SVC		\$1,286.90 X
1PC	FRONT BRAKE BOOSTER SWITCH	CNE	182.30	\$299.80 ✓
1PC	FRONT SUPPORT PANEL	Buf/Twi	605.10	\$611.20 ✓
1PC	AIR CON CONDENSER	NA		\$1,245.20 X
				\$18,808.90
S.NETT				
1PC	BONNET STICKER	NA		\$150.00 X
1SET	FRONT BUMPER CLIPS	rec		\$50.00 ✓
1PC	FRONT DOOR VISOR O/S	rec		\$80.00 50
1PC	FRONT DOOR OUTER CHROME LOWER MOULDING O/S	rec		\$150.00 100
TO CHECK WIRING				\$50.00 30
TO TRANSFER FRONT DOOR MECHANISM				\$100.00 60
TO DISMANTLE & REFIX FRONT DASHBOARD				\$380.00 200
TO SPRAY RUST PROOFING				\$120.00 100

TO REFILL AIR CON GAS
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

11 \$120.00 X
\$1,800.00 1000
\$1,580.00 900
TOTAL \$23,388.90

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-10215-88
252
9-7661-88
S.N- 200-00
L- 2290.00
10157-88
202
8171.80