

EVER SEN AUTO SERVICE

BLK 3022A UBI ROAD 1 #01-49

SINGAPORE 408716

Tel No. : 67437111 Fax No. : 67489611

E-Mail : eversenauto@singnet.com.sg

Buss. Reg. No. : B24044500/K

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET, #04-#05 IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 63476100 Fax No. : 62244174

Estimate : TI21/011

Date : 21/04/2021

Vehicle Num. : SMV 178 B

Make/Model : AUDI A5

Chassis/Eng# :

Accident Date : 13/04/2021

Claim No. :

Reference :

Policy No. :

TP III

Jasper

S/N	Quantity	Particular	Unit Price	Amount S\$
1		NETT ITEMS :		
3		BUMPER - REAR <i>Distord</i>		
2		REVERSING SENSOR <i>new</i>		
1		BUMPER RETAINER <i>Lit Damd</i>		
		BUMPER REINFORCEMENT - REAR <i>new</i>		
		FENDER - REAR LH <i>Distord</i>		
		SPLASH SHIELD <i>torn</i>		
		WHEEL RIM <i>cut</i>		
		TYRE <i>new</i>		
		WHEEL HUB BEARING - REAR <i>3 new</i>		
		TRAILING ARM L/H & R/H		
		TAIL LAMP - LH <i>cracked</i>		
		Nett Total S\$:		
		LABOUR :		
		ACCIDENT REPAIR PANEL BEATING		
		RESPRAY PAINT WORK ON REPAIR AREA		
		CONDUCT WHEEL ALIGNMENT		
		UC. UNDER CARRIAGE REPAIR & REPLACE		
		RUSTPROOFING TREATMENT		
		Labour Total S\$:		

335.00 ✓ 2,513.00
105.00 ✓ 1,005.00
✓ 105 210.00
✓ 460.00
✓ 2,520.00
✓ 135.00
✓ 1,015.00
✓ 475.00
✓ 850.00
✓ 355.00
✓ 380.00
9,918.00

800 2,800.00
500 1,000.00
80 120.00
80 300.00
80 200.00
4,420.00

6668
6001.20

1460

Total S\$: 14,338.00

=====

EVER SEN AUTO SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 7461.20

L/S: S-S/K

06 Days.