

AP AUTOMOTIVE SERVICES PTE LTD
 ROC: 202022890H
 BLOCK 9006
 TAMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

AP

Automotive Services

- KK Auto Computers have noted the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimation

Date
 Vehicle SMX 3534 B
 Make/Model HONDA SHUTTLE
 Chassis No. GK82100200

Acknowledged by Repairer

No.	Description	Unit	Unit Price	Amount
Signature: _____				
Date: _____				
Parts Replacment				
1	TAILGATE	1		\$ 66 -
2	TAILGATE WINDSCREEN MOULDING	1	\$ 126.75	\$ 126.75
3	TAILGATE LAMP L+R	2		\$ 24.00 R4 x -
4	TAILGATE OUTER GARNISH	1	\$ 347.70	\$ 347.70
5	TAILGATE CHROME	1	\$ 385.65	\$ 385.65
6	TAILGATE LOGO - HONDA	1	\$ 79.20	\$ 79.20
7	TAILGATE HANDLE SWITCH	1	\$ 267.90	\$ 267.90
8	TAILGATE NUMBER PLATE LAMP L+R	2	\$ 85.30	\$ 170.60
9	TAILGATE LOCK	1		\$ X -
10	TAILGATE LOCK CATCH	1	\$ 75.50	\$ 75.50
11	TAILGATE INNER TRIM	1	\$ 237.81	\$ 237.81
12	TAILGATE INNER HANDLE	1	\$ 45.80	\$ 45.80
13	TAILGATE HINGE SET	2	\$ 95.20	\$ 190.40
14	TAILGATE DAMPER SET	2	\$ 179.85	\$ 359.70
15	TAILGATE WEATHERSTRIP	1	\$ 149.70	\$ 149.70
16	TAIL LAMP L+R	2		\$ 24.00 R4 x -
17	TAIL LAMP PANEL L+R	2	\$ 214.25	\$ 428.50
18	REAR BUMPER	1		\$ 0 -
18	REAR BUMPER CHROME	1		\$ 0 -
19	REAR BUMPER REFLECTOR L+R	2	\$ 70.60	\$ 141.20
22	REAR BUMPER REVERSE SENSOR SET	2	\$ 172.45	\$ 344.90
23	REAR BUMPER TOW COVER	1	\$ 85.90	\$ 85.90
24	REAR BUMPER RETAINER L+R	2	\$ 80.20	\$ 160.40
25	REAR BUMPER BRACKET	1	\$ 105.23	\$ 105.23
26	REAR BUMPER UNDERCOVER	1	\$ 472.45	\$ 472.45
27	REAR FENDER LH	1		\$ 0 -
27	REAR FENDER INNER PANEL LH	1		\$ 0 -
28	REAR FENDER INNER TRIM TOP LH	1		\$ 0 -
28	REAR FENDER INNER TRIM BOTTOM LH	1		\$ 0 -
29	REAR FENDER COWLING L+R	2	\$ 105.90	\$ 211.80
30	REAR WHEELHOUSE LH	1		\$ 0 -
30	END PANEL	1		\$ 0 -
32	END PANEL TOP GARNISH	1	\$ 134.10	\$ 134.10
33	REAR SMART LOCK ANTENNA	1	\$ 194.50	\$ 194.50
34	REAR BUZZER	1	\$ 145.70	\$ 145.70
35	SPAREWHEEL PANEL	1		\$ 0 -
36	SPAREWHEEL PANEL TOP BOARD	1		\$ 0 -

37	SPAREWHEEL PANEL TOOLS SPONGE	1	\$ 143.90	\$ <i>de</i>	143.90
38	SPAREWHEEL PANEL ACCESSORIES TRAY	1	\$ 411.25	\$ <i>de</i>	411.25
39	SPAREWHEEL PANEL ACCESSORIES TRAY FRONT COVER	1	\$ 178.70	\$ <i>x</i>	178.70
40	REAR CHASSIS LH	1		\$ <i>Ry</i>	-
	<i>rear fender RH RX</i>			\$	5,595.24
			Less 20%	\$	1,119.05
			Total	\$	4,476.19

	S/Nett Items				
1	TAILGATE WINDSCREEN SEALANT	1	150	\$ <i>600</i>	150.00
2	TAILGATE INNER TRIM CLIPS	1	100	\$ <i>200</i>	100.00
3	REVERSE CAMERA	1	800	\$ <i>x</i>	800.00
4	TAIL LAMP CLIPS	1	50	\$ <i>200</i>	50.00
5	TAIL LAMP PANEL SEALANT	1	120	\$ <i>x</i>	120.00
6	REAR NUMBER PLATE	1	120	\$ <i>x</i>	120.00
7	REAR BUMPER CLIPS	1	100	\$ <i>300</i>	100.00
8	REAR FENDER SEALANT	1	250	\$ <i>500</i>	250.00
9	REAR FENDER WINDOW SEALANT	1	200	\$ <i>500</i>	200.00
10	REAR FENDER INNER PANEL SEALANT	1	250	\$ <i>x</i>	250.00
11	REAR FENDER INNER TRIM CLIPS	1	200	\$ <i>200</i>	200.00
12	REAR FENDER COWLING CLIPS	1	100	\$ <i>100</i>	100.00
13	REAR WHEELHOUSE SEALANT	1	200	\$ <i>x</i>	200.00
14	END PANEL SEALANT	1	200	\$ <i>400</i>	200.00
15	END PANEL TOP GARNISH CLIPS	1	100	\$ <i>x</i>	100.00
16	SPAREWHEEL PANEL SEALANT	1	300	\$ <i>x</i>	300.00
17	REAR CHASSIS SEALANT	1	300	\$ <i>x</i>	300.00
			Total	\$	3,290.00

	LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	3000	\$ <i>1200/600</i>	3,000.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1800	\$ <i>1000/200</i>	1,800.00
3	TO RNR REAR WINDSCREEN	1	350	\$ <i>120</i>	350.00
4	TO RNR REAR EXHAUST	1	250	\$ <i>x</i>	250.00
6	TO CHECK WIRING AND TAILLAMP FUNCTION	1	150	\$ <i>30</i>	150.00
7	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	1	150	\$ <i>30</i>	150.00
8	TO RNR REAR INNER TRIM AND UPHOISTERY	1	400	\$ <i>60</i>	400.00
9	TO CHECK WHEEL ALIGNMENT AND ADJUST	1	250	\$ <i>x</i>	250.00
10	TO RNR UNDERCARRIAGE	1	250	\$ <i>x</i>	250.00
11	TO CHECK WATER LEAK	1	150	\$ <i>20</i>	150.00
12	TO RNR FUEL TANK	1	250	\$ <i>x</i>	250.00
13	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	600	\$ <i>x</i>	600.00
14	TO RNR REAR TAILGATE MECHANISM	1	350	\$ <i>60</i>	350.00
15	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$ <i>30</i>	150.00
16	TO PERFORM RUST PROOFING	1	400	\$ <i>40</i>	400.00

Total Labour	\$	8,500.00
Parts Replacement Amount	\$	7,766.19
Total Amount	\$	16,266.19

Tanpin 27415747
up 23/4/21 @ 330pm
45 hours after repair
8 days
Tanpin @ 11/4/21