

ASS. BY:

REF:

CC4/ASM 21005024/Dga³

ASSIGNMENT

COE May 2022

From: _____ Date: _____

Estimated Cost: _____

OD / TP RES / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Work shop m/s _____

of _____

Insured _____

Policy No _____

Claim no. _____

Sum Insured: _____


Excess: _____

(Officer's Record)

Make of Vehicle: _____

(Police Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Bal. of Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / IR Seen: _____ Consistent? : Yes or No

Est. Repair: 3 days Res.: Yes or No

Turn Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBG2962A Yr Regn: May 2012

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha FZ16 C.C. 153

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: N.A. T/Radio: Insured / Std / NI / NA

Eng/No: 21C7033348

C/No: ME121C073C2033341

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70 R17

R: 130/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. mm L/Bal. mm

D.O.A. 16/04/2021 D.O.L. 22/04/2021

Survey held at SG 98 AMK

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Portm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

A7A SHC 8708D

MV 1.5K

LTA 207/-

HL 1.3K

23/11/22 Jnana HS 1.300/- with 3 days of rev

Date/Time, File Pass to?

: Prel. Report

1)

Date/Time, File Return to?

: Final Report

2)

Report Format:

Days Of Repair: _____

The survey No. of Trip: _____

Add Fee:

: Star Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 22th April 2021

To : LKK

By Fax:

Attn : Bryan

Tel :

VEHICLE NO : FBG 2962A


Yamaha FZ16

ACCIDENT DATE: 16/04/2021

Description	Qty	Quotation \$
1 Fork Bracket <i>distorted Dam</i>	1	190.00 <i>X</i> ✓
2 Handle Bar <i>distorted</i>	1	135.00 <i>X</i> ✓
3 Fork Tube <i>distorted</i>	1 set	480.00 <i>X</i> ✓
4 Mirror <i>4/5 cut</i>	1 set	160.00 <i>X</i> ✓ <i>80.00</i>
5 Balancer <i>4/5 cut</i>	1 set	150.00 <i>X</i> ✓ <i>75.00</i>
6 Clutch Lever/brake universal <i>cut</i>	1 set	190.00 <i>X</i> ✓ <i>95.00</i>
7 Front LH Signal <i>cut</i>	1	90.00 <i>X</i> ✓
8 Headlamp <i>Scratched</i>	1	350.00 <i>X</i> ✓
9 Headlamp Guard <i>cut</i>	1	195.00 <i>X</i> ✓
10 Front Mudguard <i>very cut / broken</i>	1	250.00 <i>X</i> ✓
11 Front LH Shroud <i>cut</i>	1	190.00 <i>X</i> ✓
12 Front LH Tank Cover <i>cut fage</i>	1	180.00 <i>X</i> ✓
13 Raer Tail Panel <i>cut</i>	1	190.00 <i>X</i> ✓
14 Main Stand <i>cut</i>	1	150.00 <i>X</i> ✓
Sub-Total		2,900.00
Less 10%		290.00
Sub-Total		2,610.00

2320.00

10% 208.00



VEHICLE NO : FBG 2962A

Yamaha FZ16

Nett items

1	Towing fees	44	80.00	X
2	Remove & replace necessary parts, align back the same & etc		280.00	150/-
3	Rear Box	cut	320.00	150/-
4	Remove & replace fork tube & top up fork oil	500.00	180.00	80/-
5	Putty & touch up paint work		200.00	120/-

Sub-Total 1,060.00

Nett Total 3,670.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you


2588.00
R/S 1,300/-

SG 98 MOTOR PTE LTD

22/04/2021 @ 1635hr

LKK Auto

2/3 hr 3 days



LKK Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: