

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

MS First Capital Insurance Ltd

36 Robinson Road
 #16-01 City House
 Singapore 068877
 Tel : 6507 - 3848
 Fax : 6507 - 3849

Justin

Quotation

DATE : 21.04.2021
 VEH NO : SMT3341L
 MODEL : Toyota Hiace
 D O A : 19.04.2021
 YR REF : YP1106S

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMT3341L (TOYOTA HIACE)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Rehnd</i>	1	545.40 ✓
2	Front Bumper Side Holder - RH <i>new</i>	1	55.80 ✓
3	Head Lamp - RH <i>changed</i>	1	708.60 ✓
4	Front Corner Panel - RH <i>Dented</i>	1	386.50 ✓
5	Front Door - RH <i>Don</i>	1	1,445.40 ✓
6	Front Door Hinges - RH <i>new</i>	2	161.40 +
7	Front Door Wing Mirror - RH <i>missing</i>	1	654.90 ✓
8	Front Door Glass - RH <i>lt</i>	1	561.40 ✓
9	Front Door Glass Outer Moulding - RH <i>lt</i>	1	282.30 ✓
10	Bonnet <i>Rep</i>	1	707.90 +
11	Bonnet Logo <i>new</i>	1	68.50 ✓
12	Front Grille <i>new</i>	1	598.20 +

4708.80
3531.60

Less 25%

6,176.30
 (1,544.08)
 \$ 4,632.23

S/NET ITEMS

1	Front Bumper Clips <i>new</i>	1 set	\$ 30.00 ✓
2	Front Bumper Sensor <i>new</i>	1 set	\$ 280.00 +
3	Front Door Sticker (A804) - RH <i>new</i>	1 set	\$ 100.00 60.
4	Bonnet Sticker (Emergency Ambulance) <i>new</i>	1 set	\$ 380.00 250.
5	Front Grille Clips <i>new</i>	1 set	\$ 20.00 +

340

Total Parts

\$ 810.00
 \$ 5,442.23

LABOUR CHARGE

RE : ESTIMATE FOR ACCIDENT REPAIR SMT3341L (TOYOTA HIACE)

1	To knocking & pull out RH side portion & renew above parts	\$	800.00 600
2	To putty & spray up paint works	\$	1,000.00 600
3	To check wiring	\$	50.00 30
4	To remove front bumper sensor	\$	100.00 50
5	To spray tuff coat	\$	150.00 40
6	To transfer door fittings	\$	150.00 80
Total Labour		\$	2,250.00
Grand Total		\$	7,692.23

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 5271.60
L/S: A 21K
05 Days.