

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

19-Apr-21

Our ref : TP/4975/21

Koh Boon Chye

TPA 19.

Justin.

RE : estimate cost for vehicle no : SGW 4100P

1 pc	bootlid <i>Buckled</i>	\$	895.00	✓
1 pc	logo emblem		75.00	✓
1 pc	2.4 emblem <i>1M</i>		45.00	✓
1 pc	Camry emblem <i>1M</i>		58.00	✓
1 pc	bootlid lock <i>2nd</i>		380.00	✓
1 pc	bootlid w/strip <i>new</i>		225.00	+
2 pcs	bootlid reflector <i>new LH at</i>	4719.60	790.00	+ 395.
2 pcs	taillamp <i>LH at</i>	3539.70	1,140.00	570.
1 pc	rear bumper <i>Distorted</i>		665.00	✓
2 pcs	rear bumper retainer long <i>new</i>		120.00	✓
2 pcs	rear bumper retainer short <i>not new</i>		104.00	+
2 pcs	rear bumper reflector <i>LH at</i>		115.20	57.60
6 pcs	rear bumper clips <i>new</i>		30.00	✓
1 pc	rear bumper reinforcement <i>Distorted</i>		395.00	✓
1 pc	end panel <i>Distorted</i>		695.00	✓
1 pc	end panel inner garnish <i>2nd</i>		400.00	339
1 pc	spare tyre cardboard <i>new</i>		400.00	+
1 pc	spare tyre panel <i>Repair</i>		880.00	+
			7,412.20	
less 25%			1,853.05	
			5,559.15	
1 pc	reverse sensor <i>Damaged</i>	200	250.00	nett 200.
Panel beating.			1200.00	1000
Spray painting.			1200.00	800.
Wiring.			30.00	✓
Rust proofing.			80.00	60
			8319.15	
Plus 7% GST			582.34	
			8901.49	

SD : Eight thousand nine hundred one & cents forty-nine only.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King.
2/s 20/04/21

OT Pays.

total: 5629.70
A/S: 4.5K.