

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0339/2021/NK
DATE : 20-Apr-21
WIP : 23601

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/4/21

YOUR INSURED VEH NO : SLG 4090 J

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS FU WAN PEI CHERYLIN
ADDRESS : BLK 766 BEDOK RESERVOIR ROAD
#14-23
SINGAPORE 479248
TELEPHONE : HP +6596191025
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100485002-04
VEHICLE NO : **SLG 4090 J**
MODEL CODE : TT COUPE 2.0 TFSI QU
MODEL YEAR : 29-09-2016
ENGINE NO : CHH119261
CHASSIS NO : TRUZZZFV9G1010931
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Apr-21
PLACE OF ACCIDENT : PIE CHANGI, JUST BEFORE EXIT 9 JALAN EUNOS

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLG 4090 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000 ✓
4	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$ 2,400.00	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 5,872.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLG 4090 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Deformed</i>	1	\$ 2,506.00	✓	<i>2004.80</i>
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 486.00	+	
3	FRONT BUMPER CLOSING ELEMENTS LH / RH <i>Not mee</i>	2	\$ 222.00	? X	
4	FRONT GRILLE - CENTER <i>cracked</i>	1	\$ 161.00	✓	<i>128.40</i>
5	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE <i>new</i>	1	\$ 156.00	+	
6	AIR GUIDE GRILLE LH / RH <i>cracked</i>	2	\$ 434.00	? X	<i>346.40</i>
7	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,359.00	✓	<i>1087.20</i>
8	ULTRASOUND SENSOR TRIM LH / RH <i>new</i>	2	\$ 68.00	+	
9	AUDI "QUATTRO" EMBLEM <i>new</i>	1	\$ 99.00	✓	<i>79.04</i>
10	AUDI "QUATTRO" BRACKET <i>Not mee</i>	1	\$ 68.00	? X	
11	RADIATOR GRILLE CENTRE COVER <i>Not mee</i>	1	\$ 107.00	? X	
12	ULTRASOUND SENSOR BRACKET LH / RH <i>new</i>	2	\$ 96.00	+	
13	FRONT BUMPER COVER LH / RH <i>Deformed</i>	2	\$ 112.00	? X	<i>89.44</i>
14	FRONT BUMPER COVER CENTRE <i>Not mee</i>	1	\$ 65.00	? X	
15	FRONT BUMPER SUPPORT ELEMENT <i>Not mee</i>	1	\$ 35.00	? X	
16	FRONT BUMPER FOAM <i>Not mee</i>	1	\$ 129.00	? X	
17	FRONT REINFORCEMENT BEAM <i>Not mee</i>	1	\$ 1,084.00	? X	
18	FRONT REINFORCEMENT GUIDE SECTION LH / RH <i>new</i>	2	\$ 78.00	+	
19	FRONT BUMPER REINFORCEMENT COVER <i>Not mee</i>	1	\$ 127.00	? X	
20	"CAUTION" SIGNAGE <i>Not mee</i>	1	\$ 14.00	X X	
SUB TOTAL SPARE PARTS		:	\$ 7,406.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLG 4090 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	AIR CONDITIONER STICKER <i>Not</i>	1	\$ 8.00	<i>+</i> <i>X</i>	
22	FRONT BUMPER INNER SENSOR <i>3</i>	2	TBC	<i>+</i>	
23	FRONT BUMPER SENSOR SEAL RING <i>an</i>	4	\$ 14.00	<i>+</i>	
24	BONNET <i>Dented</i>	1	\$ 4,357.00	<i>✓</i> <i>3485.60</i>	
25	BONNET ATTACHMENTS PARTS <i>an</i>	1	\$ 102.00	<i>+</i>	
26	BONNET HINGE LH / RH <i>an</i>	2	\$ 684.00	<i>+</i>	
27	BONNET IMPACT PROTECTION LH/ RH <i>an</i>	1	\$ 102.00	<i>✓</i> <i>80.64</i>	
28	BONNET EDGE PROTECTION <i>an</i>	1	\$ 30.00	<i>✓</i> <i>2H</i>	
29	BONNET STRIKER LH / RH <i>an</i>	2	\$ 212.00	<i>+</i>	
30	BONNET COVER <i>an</i>	1	\$ 10.00	<i>+</i>	
31	BOWDEN CABLE - CENTER <i>2</i>	2	\$ 58.00	<i>+</i>	
32	BONNET LOCK SWITCH	2	\$ 399.00	<i>+</i>	
33	BOWDEN CABLE SIDE <i>an</i>	1	\$ 58.00	<i>+</i>	
34	BONNET RELEASE LEVER	1	\$ 14.00	<i>+</i>	
35	LED MATRIX HEADLIGHT LH / RH <i>an</i>	2	\$ 22,162.00	<i>+</i>	
36	LIFT CYLINDER LH / RH <i>2</i>	2	\$ 318.00	<i>+</i>	
37	LIFT CYCLINDER HOSE <i>an</i>	1	\$ 77.00	<i>+</i>	
38	RADIATOR AIR GUIDE LH / RH	2	\$ 72.00	<i>+</i>	
39	RADIATOR AIR GUIDE SEAL RH OUTER <i>2</i>	1	\$ 8.00	<i>+</i>	
40	WHEEL HOUSING LINERS LH / RH <i>an</i>	2	\$ 234.00	<i>+</i>	
SUB TOTAL SPARE PARTS		:	\$ 28,919.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLG 4090 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	AUDI CHROME LOGO <i>Alu</i>	1	\$ 138.00	✓ 110
42	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓ 60
43	SUNDRIES <i>Nec.</i>	1	\$ 250.00	? <i>27.44</i>
TOTAL SPARE PARTS		:	\$ 36,773.00	
TOTAL LABOUR CHARGES		:	\$ 5,872.00	
GRAND TOTAL		:	\$ 42,645.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *21/04/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*
H.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Veron.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TP/0339/2021/NK

10-May-21

CHANG

1 of 1

SLG 4090 J

AUDI TT COUPE 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT WHEEL HOUSING LINER SECURING STRIP - LH/RH <i>Nec</i>	\$ 86.00	✓ 68
GRAND TOTAL		\$ 86.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
11/05/21 *[Signature]*