



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

QBE INSURANCE (S) PTE LTD

INV No. AC2202519

1 RAFFLES QUAY #29-10 SOUTH TOWER  
SINGAPORE 048583

INV Date 05/05/2022  
Reference CC4/QBE21005044/Aea3q2  
Code QBE

### PROFESSIONAL SERVICE FEE

Vehicle No. SMP 7909U  
Insured Veh. SLV 9151E  
Claim No. VC014472  
Policy No. 8-V0014149-MVA-R003  
Accident Date 19/04/2021  
Inspection Date 22/04/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (S) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC4/QBE21005044/Aea3q2	
			Date: 05/05/2022	
			Code: QBE	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLV 9151E	Veh. Inspected	SMP 7909U	
Policy No.	8-V0014149-MVA-R003	Coverage (\$)	0.00	
Claim No.	VC014472	Excess (\$)	0.00	
Assign From	JENNY	Assign Date	22/04/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	AUDI A3	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WAUZZZ8V8LA002754	Colour	SILVER	
Odometer	16972 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/04/2021	Inspection Date	22/04/2021	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 7909U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (SN)	DEFORMED	1,944.00	1,944.00
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	193.00	-
2	REAR BUMPER GUIDE SECTION -LH/RH (SN)	NOT NECESSARY	32.00	-
1	REAR BUMPER SPOILER (SN)	NOT NECESSARY	237.00	-
1	REAR BUMPER REINFORCEMENT BEAM (SN)	NOT NECESSARY	603.00	-
2	REAR BUMPER BRACKET -LH/RH (SN)	NOT NECESSARY	56.00	-
1	SUNDRIES (SN)	NOT NECESSARY	200.00	-
			3,265.00	1,944.00
	<b><u>LABOUR</u></b>			
	TO REMOVE AND RENEW REAR PARKING AND CHECK FUNCTION.		280.00	280.00
	TO DISMANTLE AND RENEW BUMPER RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED.		1,050.00	700.00
	TO RESPRAY REAR BUMPER .		900.00	700.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			2,422.00	1,872.00
	<b>GRAND TOTAL</b>		<b>5,687.00</b>	<b>3,816.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>3,816.00</b>

Report Ref No. CC4/QBE21005044/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMP 7909U

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

