

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0346/2021/HR
DATE : 21-Apr-21
WIP : 24219

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 22/4/2021

YOUR INSURED VEH NO : SLV 9151 E

QBE Insurance (International) Ltd

60 Anson Road

#11-01, Mapletree Anson

Singapore 079914

Attn: Motor Claims Dept

Fax: 6534 5356

OWNER'S NAME : MR CHANG MING'EN SAMUEL
ADDRESS : 11 LEEDON HEIGHTS
#27-35
SINGAPORE 267955
TELEPHONE : HP +65 87483770
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900198696-01
VEHICLE NO : **SMP 7909 U**
MODEL CODE : A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 19/10/2019
ENGINE NO : CHZ C35208
CHASSIS NO : WAUZZZ8V8LA002754
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Apr-21
PLACE OF ACCIDENT : NEAR PORTSDOWN ROAD.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 7909 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND RENEW REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	
2	TO DISMANTLE AND RENEW BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	
3	TO RESPRAY REAR BUMPER.	\$	900.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 2,422.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 7909 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,944.00	
2	REAR BUMPER FIXING PARTS	1	\$ 193.00	
3	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 32.00	
4	REAR BUMPER SPOILER	1	\$ 237.00	
5	REAR BUMPER REINFORCEMENT BEAM	1	\$ 603.00	
6	REAR BUMPER BRACKET - LH / RH	2	\$ 56.00	
7	SUNDRIES		\$ 200.00	
TOTAL SPARE PARTS		:	\$ 3,265.00	
TOTAL LABOUR CHARGES		:	\$ 2,422.00	
GRAND TOTAL		:	\$ 5,687.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT