

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 20/04/2021

TP Veh Reg No: SKJ5070G

Estimate No: ES2190389/AMK

Date: 26 Apr 2021

Policy No: 5058053281-08

Veh Reg No: SJN3649S

Make/Model: TOYOTA WISH 1.8 A

Chassis No: JTDER12W303001791

Engine No: 1ZZ3226141

Reg. Date: 12/02/2009

Estimate Repair Cost to Vehicle No :SJN3649S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	627.20	1 PC	627.20	✓
2 REAR BUMPER RH REFLECTOR	57.90	1 PC	57.90	✓
3 REAR BUMPER RH REINFORCEMENT BRACKET	53.80	1 PC	53.80	✓
4 REAR BUMPER RH SIDE RETAINER	69.40	1 PC	69.40	✓
5 REAR BUMPER CLIP	4.20	5 PC	21.00	✓
6 TAILLAMP	596.70	2 PC	1,193.40	✓
7 REAR TAILGATE	1,620.70	1 PC	1,620.70	✓
8 TAILGATE INNER LOCK	539.90	1 PC	539.90	✓
9 TAILGATE INNER RUBBER	369.90	1 PC	369.90	✓
10 TAILGATE INNER TRIM BOARD	373.80	1 PC	373.80	✓
11 TAILGATE WINDSCREEN GLASS MOULDING	70.20	1 PC	70.20	✓
12 TAILGATE LOGO	49.27	1 PC	49.27	✓
13 REAR END PANEL	590.60	1 PC	590.60	✓
14 REAR END PANEL INNER TOP GARNISH	283.70	1 PC	283.70	✓
			5,920.77	
		Less 25%	1,480.19	4,440.58
Special Net				
15 REVERSE SENSOR	200.00	1 PC	200.00	✓
16 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
17 REAR BUMPER STEP GARNISH	80.00	1 PC	80.00	✓
18 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
19 REAR END PANEL SEALANT	40.00	1 PC	40.00	✓
			395.00	395.00
Labour				
20 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILGATE & ATTACHMENTS, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR LUGGAGE PANEL, REAR FENDERS & REALIGN THE SAME	900.00	1 LA	900.00	600
21 PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS, TAILGATE BOTH FENDERS, REAR END PANEL, REAR LUGGAGE PANEL & ALL AFFECTED AREAS	900.00	1 LA	900.00	720
22 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
23 RUSTPROOFING	90.00	1 LA	90.00	60
			2,010.00	2,010.00

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 20/04/2021
TP Veh Reg No: SKJ5070G

Estimate No: ES2190389/AMK
Date: 26 Apr 2021
Policy No: 5058053281-08
Veh Reg No: SJK3649S
Make/Model: TOYOTA WISH 1.8 A
Chassis No: JTDER12W303001791
Engine No: 1ZZ3226141
Reg. Date: 12/02/2009

Estimate Repair Cost to Vehicle No :SJK3649S

Estimate Repair Cost to Vehicle No. 35678912				
Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	S\$ 6,845.58
			Add GST @ 7%	479.19
			Total Amount Payable	S\$ 7,324.77

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE