



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR21005048/Uuf3e2 Date: 24/05/2021 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SHB 5555C	<b>Veh. Inspected</b>	GBG 7055K
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	TAX/04/21/2034	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HUA YEN	<b>Assign Date</b>	22/04/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	ISUZU TFR86JSR	<b>c.c</b>	2499
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	MPATFR86JHT002641	<b>Colour</b>	WHITE
<b>Odometer</b>	104596 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	215/70 R15	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	215/70 R15	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	215/70 R15	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	215/70 R15	YOKOHAMA	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	13/04/2021	<b>Inspection Date</b>	27/04/2021
<b>Survey held at</b>	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	