

BM WHEELPOWER PTE LTD



Ref: GBE2962K

Ref: ES2330A

AIG

Not Authored

Runny B4 pain

4 days

11 Pm @ 3.900h

confirm 1/5 ~ \$3900/-

Date: 21/4/2021
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: B.M.W 216D
Chassis No.: WBA2E320005B44921
Engine No.: 30219523B37C15A
Year of Make: 2016
Accident Date: 17 April 2021

ESTIMATE FOR VEHICLE NO.: ES2330A

DESCRIPTION

DESCRIPTION	QTY	List Price
FRONT BUMPER <i>1220</i>	1	\$ <i>Buc</i> 1,700.00 ✓
FRONT BUMPER RH RETAINER	1	\$ <i>in</i> 55.00 X
FRONT RH FOG LAMP BRACKET	1	\$ <i>CM</i> 175.00 ✓
FRONT RH FOG LAMP CHROME <i>125.00</i>	1	\$ <i>any</i> 157.00 ✓
FRONT RH FOG LAMP COVER <i>127.80</i>	1	\$ <i>DIY</i> 143.00 ✓
FRONT RH FOG LAMP <i>245</i>	1	\$ <i>m/cm</i> 325.00 ✓
PARKING SENSOR - BLACK	2	\$ <i>in</i> 640.00 X
DECOUPLING RING	4	\$ <i>in</i> 60.00 X
HEAD LAMP RH <i>2359.75</i> <i>63117391404</i>		\$ <i>CM</i> 3,060.00 ✓
Total:		\$ 6,315.00
LESS 10%		\$ (631.50)
Parts Total:		\$ 5,683.50

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	<i>3501</i> 800.00
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	300.00 <i>200</i>
TO REMOVE & REPLACE BUMPER SENSORS	\$	60.00 ✓
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	<i>201</i> 80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	<i>4401</i> 800.00
Total:	\$	7,723.50
7% GST:	\$	540.65
Grand Total:	\$	8,264.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

162628888 f 64525333

Company Registration Number : 200204110W