



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE #03-03  
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS/SMO21005050/Uvf3n2

Date: 04/05/2021

Code: SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBF 4891M	<b>Veh. Inspected</b>	SKJ 4639Z
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2101102/AGC	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GARCE TEO	<b>Assign Date</b>	22/04/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	BMW 520D (A)	<b>c.c</b>	1995
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2013
<b>Chassis No.</b>	WBAFW12050D164636	<b>Colour</b>	BLACK
<b>Odometer</b>	202573 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/55 R17	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	225/55 R17	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	225/55 R17	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	225/55 R17	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	02/04/2021	<b>Inspection Date</b>	26/04/2021
<b>Survey held at</b>	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**