



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

M/S : AIG Asia Pacific Insurance Pte Ltd
(MOTOR CLAIM DEPARTMENT)

Email aigsgp_claimssurvey@aig.com

Justin.

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No:	SFP8181C	Date:	22.04.2021
Vehicle Model:	HYUNDAI TUCSON	Reg. Date:	16.12.2020
Chassis No:	KMHJ3812VLU379646	D.O.A:	21.04.2021

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Front Bonnet	1	\$ 1,852.30	\$ 1,852.30	+
2	Front Bonnet Insulator	1	\$ 224.30	\$ 224.30	+
3	Front Bonnet Rubber Seal	1	\$ 85.00	\$ 85.00	+
4	Front Headlamp RH	1	\$ 5,867.80	\$ 5,867.80	✓
5	Front Headlamp Bracket RH	1	\$ 98.30	\$ 98.30	+
6	Front Headlamp Top Garnish RH	1	\$ 85.40	\$ 85.40	+
7	Front Bumper	1	\$ 559.50	\$ 559.50	✓
8	Front Bumper Lower	1	\$ 431.40	\$ 431.40	✓
9	Front Bumper Side Retainer RH	1	\$ 68.40	\$ 68.40	✓
10	Front Bumper Attachment Bracket	1	\$ 98.30	\$ 98.30	✓
11	Front Bumper Tow Cover	1	\$ 42.60	\$ 42.60	+
12	Front Bumper Lower Lid	1	\$ 245.60	\$ 245.60	+
13	Front Number Plate Garnish	1	\$ 65.30	\$ 65.30	+
14	Front Bumper Radiator Grille	1	\$ 751.80	\$ 751.80	✓
15	Front Bumper Radiator Grille Logo	1	\$ 85.30	\$ 85.30	+
16	Front Bumper Sensor	4	\$ 169.00	\$ 676.00	+
17	Front Bumper Sensor Garnish	1	\$ 138.60	\$ 138.60	+
18	Front Bumper Fog Lamp RH	1	\$ 757.10	\$ 757.10	+
19	Front Bumper Fog Lamp Garnish RH	1	\$ 126.40	\$ 126.40	✓
20	Front Bumper Reinforcement	1	\$ 653.60	\$ 653.60	✓

C/F \$ 12,913.00



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F \$ 12,913.00

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
21	Front Bumper Reinforcement Sponge <i>new cable</i>	1	\$ 141.20	\$ 141.20	<i>✓</i>
22	Front Bumper Lower Stiffener <i>new</i>	1	\$ 224.90	\$ 224.90	<i>+</i>
23	Front Support Panel <i>new</i>	1	\$ 987.80	\$ 987.80	<i>+</i>
24	Front Support Panel Top Garnish <i>new</i>	1	\$ 265.80	\$ 265.80	<i>+</i>
25	Front Support Panel Air Guide RH <i>new</i>	1	\$ 64.20	\$ 64.20	<i>+</i>
26	Wiper Washer Tank Assy <i>delid</i>	1	\$ 130.70	\$ 130.70	<i>✓</i>
27	Wiper Washer Tank Motor <i>new</i>	1	\$ 89.50	\$ 89.50	<i>+</i>
28	Front Fender RH <i>new</i>	1	\$ 1,227.70	\$ 1,227.70	<i>+</i>
29	Front Fender Protector RH <i>cut</i>	1	\$ 195.20	\$ 195.20	<i>✓</i>

Total For List Items: \$ 16,240.00

Less Spare Parts Discount (20%): \$ 3,248.00

Total: \$ 12,992.00

C/F \$ 12,992.00

9024-30

7219-44



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F \$ 12,992.00

SPECIAL NETT ITEMS

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Front Number Plate W Casing <i>Not</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
2	Bonnet Insulator Clips 1set <i>Not</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
3	Front Bumper Clips 1set <i>Not</i>	1	\$ 30.00	\$ 30.00	<i>✓</i>
4	Support Panel Top Garnish Clips 1set <i>Not</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
5	Front Fender Clips 1set <i>Not</i>	1	\$ 30.00	\$ 30.00	<i>+</i>

Total For S/N Items: \$ 180.00

30

LABOUR

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	To panel beat/straighten/realign accident affected areas	1	\$ 1,500.00	\$ 1,500.00	<i>300</i>
2	To respray accident affected portion.	1	\$ 1,200.00	\$ 1,200.00	<i>400</i>
3	To dismantle, replace and/or repair air con condenser & refill air con gas	1	\$ 150.00	\$ 150.00	<i>X</i>
4	To dismantle, replace and/or repair radiator and pressure test	1	\$ 150.00	\$ 150.00	<i>X</i>
5	To check wiring/wire connector and rewire/repair	1	\$ 100.00	\$ 100.00	<i>30</i>
6	To check and realign headlamp	1	\$ 100.00	\$ 100.00	<i>X</i>

Total For Labour: \$ 3,200.00

Grand Total: \$ 16,372.00

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Authorised by Repairer

total: 7979.44 *Adrian*
L/S: 6.3K. *2/s 23/04/21*
04 Days.